# Certificate of Location of Government Corner

**ID#:** 543004 **Description:** 1/4 SEC COR 30 31 **Date Set:** 7/2/2007 **County:** Olmsted

**Section:** 30 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 7 1/2' west of the centerline of N-S twp road and in line with fence east
Center of the No. plate on PP #10786 SSE 142.1'
This corner is located by GPS measurement

**Corner History:**

1853 Gov't notes, Yerby; 40.0 set temp 1/4 section post. On true line between sections 30-31. 39.60 set 1/4 section post in mound of earth, sod, deposited charcoal, made trench with pits, and planted osage orange seeds N & S.

4-1884 T. Hunter (BK. A pg. 388) set a stake on line with the section corners and at gov't proportions.

10-1888 T. Hunter (BK. A pg. 425) found his old stake and set a new stake and boulder.

6-9-1971 County Surveyor found center 30 stone which came 1.42' east of random N-S 1/4 line tied down as short 1/2" rod between hubs.

6-14-1971 County Surveyor set long sash weight below CIM. Corner 4.5' east of west edge traveled road and 6' west of center edge traveled road. RPs- NW corner of E culv. Headwall SSE 245.9, center number plate #10786 PP SSE 142.1, N-S fence on east edge road E 39.7.

1982 County Surveyor found and shot CIM ok. See DWG 5-17.

8-30-2000 WHKS survey crew notes that CIM is broken.

9-7-2004 County Surveyor found CIM without head down 1.3' in good condition.

12-14-2004 County Surveyor found CIM with head broken off down 1.3' in good condition.

6-28-2007 County Surveyor found CIM w/o head down 1.2' in good condition.

7-2-2007 County Surveyor removed CIM w/o head and found sash weight down 1.8' in good condition. Removed sash weight and set 6' telspar pipe w/cast iron cap down 0.5' at CIM position.