Certificate of Location of Government Corner

ID#: 543009 **Description:** SEC CEN 30 54 **Date Set:** 6/9/1971 **County:** Olmsted

Section: 30 **Township:** 105N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
5/8" rerod

Reference Ties:

The corner falls in centerline of twp road south and in centerline of E-W twp road
This corner is located by GPS measurement

Corner History:

10-9-1888 T. Hunter (BK. A pg. 425) set a boulder on intersecting lines.

6-4-1892 Thos. Fraser (BK. A pg. 480) found the stone.

12-1915 J. Kerr (BK. B pg. 242) found the stone.

9-1924 county highway department Bk.39 Pg.80; Found stone. RPs- spike in fence post SW 66.9, spike in tele pole SW 44.0, spike in stump SW 84.2

6-9-1971 County Surveyor found the original stone. Set rod as temp corner. Corner 3.65 E of .00 or lot fence running north. RPs- hard nail in E side white cedar corner post of fence W 4"W of N 44.82, center tele bell on iron post NE 71.0, center tele bell on iron post 42.9, 20D in top corner post fences E & S SE 45.55, corner in center road south at N end of road or little east and in center E & W roads.

1982 County Surveyor found iron ok and shot iron. See DWG 5-17.

10-15-1996 R. Brand & Associates used computed center.

4-19-1999 GGG, Inc. found and used iron at center of section 30.

8-30-2004 WHKS Survey Crew found 5/8" rebar as described.

5-11-2006 Massey Land Surveying found and used 5/8" rerod at center of section 30.

6-28-2007 County Surveyor found 5/8" rerod down 0.2' in good condition.