Certificate of Location of Government Corner

ID#: 543104 **Description:** S 1/4 SEC COR 31 54 **Date Set:** 3/9/2005 **County:** Olmsted

Section: 31 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' north of centerline of E-W twp road and 55' east of centerline of Shervin Ave SW
Large headed nail up 4' in SW side PP #5991 NW 38.07'
Center of TCM post NE 34.26'
16d nail in E side 24" Burr Oak up 5' NNW 51.3'
(Tree has a large scar at the base on the SW side)
This corner is located by GPS measurement

Corner History:

1897 Will Fraser (BK. A pg. 608) located the corner. M & L 39.93

1905 C. Armstrong found the corner.

12-1915 J.Kerr Pg.242-5 B; found no corner a iron stake as set by W. Frazer on M & L.

1-23-1938 J.Kerr Bk.12 Pg.16; Found S 1/4 31 & old iron bar. Set 1" x2' pipe over iron bar. RPs- 60Din Elm SW 135.6, 60D in 4" elm NW 92.6

6-1-1971 County Surveyor set 3/4"x10" iron over found 1"x2' iron with CIM. RPs-Up 4' on the SW side of PP #5991 is a large headed nail NW 38.10'. Center of TCM post NE 34.26', 16d nail on the E side of a 24" Burr Oak up 5' 10' W of N 51.3', (Tree has a large scar at the base an the SW side), Center of the North-South road West 55', Center line E-W Twp road South line 6'.

7-10-1978 County Surveyor found CIM with head missing, with an iron driven along side CIM. Corner falls 6' N of centerline E-W Rd.

11-2-1998 County Surveyor found CIM with head broken off down 0.8'.

Note: This is a correction of a corner- a 5/8" rod. The corner they set and recorded was 6.25' South and 1.03' East of the correct corner. The rod was removed that was set at the incorrect corner.

12-14-2004 County Surveyor found CIM with head broken off down 0.8' in good condition.

2-25-2005 County Surveyor found CIM w/o head down 0.8' in good condition.

3-9-2005 County Surveyor removed CIM and found 3/4" iron down 2.5' in good condition. Removed 3/4" iron and set 5' telspar pipe w/cast iron cap down 0.3'.

9-21-2007 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.