Certificate of Location of Government Corner

ID#: 543505 **Description:** S SEC COR 34 35 54 **Date Set:** 6/20/2002 **County:** Olmsted

Section: 35 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of 6th St SE and 32' east of centerline of 7th Ave SE
5/8" drill hole in back of curb N 22.4'
County Survey Disk in PP SSW 35.2'
Bottle cap in stub TP NE 36.66'
Nail in E side PP SSW 31.91'
Center 2" pipe most westerly post of backstop NW 97.64'
This corner is located by GPS measurement

Corner History:

Southeast Corner, Section 34, Township 105 North, Range 14 West

1853 Gov't. Notes West on South boundary of Section 35. 80.00 chs. Set post with trench for corner to Sections 34 and 35. Burr Oak 16 in. N33°W 143 lks.

6-1898 Thomas Fraser P487 No 413, County Surveyor, could not find corner. Reset a stone from measurements.

5-1902 William Fraser P16 Bk B, County Surveyor, found stone set as corner.

12-1910 Charles Larson P144 Bk B, County Surveyor, found stone and stake.

7-1930 county highway department, P4 Bk 57 found limestone in center of road.

1965 McGhie & Betts Inc. found or used stone for work west and south. Set 1/2" pipe with rod below bent to center over stone.

4-30-1970 County Surveyor found irons with stone below. Left stone and set 1/2" rod over stone. RPs- angle N to west 90°001/2', bottle cap in TP E side junction box No.414 NNE 36.66, 30d nail & red rag driven down on E side PP SSW 31.91.

8-24-1971 County Surveyor took additonal RP- 30d nail in top of corner post north in place N 28.4.

7-24-1974 Roger Brand, County Surveyor, dug down to limestone and set a cast iron monument over stone with iron pieces on the east and west sides of the stone. RPs- bottle cap in stub TP NE 36.66, nail in E side large PP SSW 31.91' center 2" pipe most westerly post of backstop NW 97.64'

3-5-1992 Yaggy Colby Associates found a cast iron monument set by Roger Brand 7-24-1974 in the center line CR 106 (6th Street SE) 0.5' below bituminous surface.

6-19-2002 County Surveyor found CIM w/head broken off down 0.6'

6-20-2002 County Surveyor measured down 1.0' to top of broken CIM. Took local ties and filled hole w/blacktop set a 1' long 1" square pipe w/cap at surface.