Certificate of Location of Government Corner

ID#: 551105 **Description:** SEC COR 10 11 14 15 55 **Date Set:** 4/22/2009 **County:** Olmsted

Section: 11 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road and in centerline of E-W twp road
County highway disk in SW side PP #6929 SE 41.89'
County Survey Disk in PP #41729 NE 43.80'
Punch hole in W end 16" CMP SE 47.67'
Punch hole in E end 16" CMP SW 50.41'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick, Deputy Surveyor North between sections 14 and 15. 80.00 chs. Set corner post and erected mound with trench, pits, and charred stake and planted osage seeds at each angle.

11-1857 John Fellows (Pg.42 No.64) shows sec. corner 1/16 West 19.89 chs. M & L to 1/4 post (see survey for interior breakdown of sec 10)

6-1898 William Fraser (P.520 No. 486), County Surveyor, found old stake in road. Set stone 3"x9"x17" as corner in place of stake. Set 1/16 north a stone 3"x10"x15" midway and on line.

7-23-1971 County Surveyor dug with tractor after finding 1/16 and 1/4 stones north. Found limestone 3"x9"x13" in dark original soil 5' deep. Set 2"x3' pipe over stone with CIM over pipe.

5-26-1972 County Surveyor removed CIM for grading.

4-22-1974 County Surveyor reset CIM over 1/2"x2' rod.

9-27-1988 County Surveyor found CIM down 1' in good condition in intersection twp roads E-W-N-S. RP's county highway department SW side of PP #6929 SE 41.82'. Spike in PP to low because of regrade other RP's ok.

4-22-2009 County Surveyor found CIM down 1.3' in good condition, took ties and removed. Found 1/2" iron rod down 2.8' in good condition, removed. Probed down another 2' and hit either pipe or stone. Set 4 1/2' telspar pipe w/Cast Iron Cap at CIM location down 0.5'.