Certificate of Location of Government Corner

ID#: 551204 **Description:** 1/4 SEC COR 12 13 55 **Date Set:** 6/29/2007 **County:** Olmsted

Section: 12 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' south of centerline of E-W twp road, 32' east of fence south and 69' east of centerline of farm entrance north
Bottle cap in NW side CP SW 58.28'
County Survey Disk in SW side PP WNW 95.12'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick, Deputy Surveyor West on true line between sections 12 and 13. 40.00 chs. Set quarter section post. Br. Oak 8 in. S87W 127 lks. Br. Oak 7 in. N28W 197 lks.

3-1858 J. Fellows (P.51 No.74) used corner.

9-1913 D. Williams (P.228 Book B), County Surveyor, could find no evidence or knowledge of corner so set a point midway and on line and corner fell in center of the east-west road.

10-2-1973 County Surveyor, Meas elect and line from nail at 11-12-13-14 R Dell. East nail at centerline road in line fence N 2647.71. Meas in 6-73 from nail East to random nail at E 12-13 R Dell 7-18 Hi For. 2624.95 total 5272.66 (R 5280) line fell .34 S of East nail. Dug from 6 or 7 West of nail to 4' East and 6 or 8' N and S. Road to near bed clay road slopes up to 300' West so road washed and wore away. Set nothing.

4-26-1974 County Surveyor dug entire area and could find no evidence of corner so set a C.I.M. midway and on line by electronic measure (2643.76).

9-27-1988 County Surveyor found CIM in good condition. 0.25' down in E-W Twp Rd 3' South of centerline. Took new RP 58.32 SW to bottle cap in NW side of corner post, CSD in South side PP# 7156 NW 96.55' other RP's gone.

6-28-2007 County Surveyor found CIM down 0.5' leaning East.

6-29-2007 County Surveyor found CIM down 0.5' leaning east, took local ties and removed. Found 1/2" iron rod down 2.1' in good condition, took local ties and removed. Set 5' telspar w/CIC down 0.55' from ties taken from rod. Updated ties.