Certificate of Location of Government Corner

ID#: 551709 **Description:** SEC CEN 17 55 **Date Set:** 6/27/2001 **County:** Olmsted

Section: 17 **Township:** 105N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1/2" pipe w/cap RLS #21940

Reference Ties:

The monument is at the surface
The corner falls 3' south of E-W fence
Post with sign west 2'
This corner is located by GPS measurement

Corner History:

6-17-1895 W. Fraser (P.579 No.529) drove stake with boulder stone by its side at ture inters lines. N-S 1/4 line bearing N 45' E. 1/16 East set stake M & L 19.91 = 1314.06 N 88° 50' W (1314.06 R). 6" Burr Oak 17 = 11.22 ft N and 1 lk East of stake.

6-1965 J. Kerr run and meas E-W 1/4 line to blacktop road East, looked for 1/16 cor. East. It lies on hillside subject to wash. Dug 6' x 10' at center 17 after running line for center found some stones, none seemed to be corner. Line brings corner 7' South of fence East half recorded as 2628.12 West half 2645.2 meas record meas. Meas 5273.0 old fence South at 3959.0 from West R 2645.2 + 1314.06 or 3949.26. Finally set CIM on line as near as possible .00 West end. S 19.31 center S 38.5 at East end assumed corner could come 5' West center blacktop road. Meas West to 1/4 cor. 2645.2 East 2627.8. Found real old post at 2647' in fence line at 12' South random line. Set CIM 7' South fence in field. Hub and nail in 18" cherry in fence line East 142.25 1 1/4" x 4 1/2' standing pipe North 4 1/2'. Monu. down 12" 1/16 fence West running South a true line fence at least 11' too far East and 6' too far North.(R North line W 1/2 17.2643.6B, South line W 1/2 172647.92) mean 2645.78 as West line straight and center with corner near right.

1-1981 County Surveyor, this CIM (Kerr's) is not on the E-W 1/4 line after we found E 1/4 cor. 17 must go .31 S.

6-1981 County Surveyor set corner on paper (see drawing 4-62).

6-27-2001 GGG set 1/2" pipe w/cap RLS #21940 at intersecting quarter lines.

10-13-2010 County survey crew found 1/2" pipe in good condition