Certificate of Location of Government Corner

ID#: 553009 **Description:** SEC CEN 30 55 **Date Set:** 5/15/2009 **County:** Olmsted

Section: 30 **Township:** 105N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' east of centerline of CR 149 and 17 1/2' south of centerline of driveway west
County highway disk in N side PP #6665 WSW 40.11'
+ cut in end CMP NW 44.50'
County highway disk in CP E 33.60'
This corner is located by GPS measurement

Corner History:

8-19-1965 J. Kerr found nothing. Set corner from intersection of lines from 1/4 corners.

5-1-1980 county highway department (Book 477 Pg7) found CIM in good condition. Took ties.

5-9-1988 Tom Ferguson found and used monument at center of section 30.

6-1-1995 Land Consultants found monument in good condition at intersecting quarter lines.

4-11-2008 M. James Associates found and used monument for survey in NE 1/4 section 30.

5-5-2009 County Surveyor found CIM down 1.4' in good condition.

5-15-2009 County Surveyor found CIM down 1.4' in good condition. Took local ties and removed. Found 5/8" x 14" rod down 3.0' in good condition and matching ties. Removed. Set 4' telspar pipe w/CIC down 0.5' at CIM position.