Certificate of Location of Government Corner

ID#: 553204 **Description:** S 1/4 SEC COR 32 55 **Date Set:** 11/7/2005 **County:** Olmsted

Section: 32 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of E-W fence
Sign on angle iron CP 1' north
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes 15.00 creek 20 lks wide runs NE. 40.00 set gr sec. post. Black Oak 6 N 40° E 49 lks. White Oak 16 N 78° W 160". 47.00 enter timber bears NW 53.70 creek 20 lks wide runs SE.

6-1875 T. Hunter (P.282 No.279) found original stake in mound. Tested by marked stumps of 2 bearing trees. 1/16 East set marked stake M&L 19.65 to original corner at SE corner 32, very short but both avered gov't corners.

6-14-1875 T. Hunter unrecorded Survey corner in place meas West 5.48 chs (361.68) to set NE corner 5 104-15, then set N 1/4 5 M&L on line with NW corner which was reset by bearing trees stumps.

6-1878 T. Hunter (P.351 No.342) found original stake in mound P.282. Meas East 39.41 to SE 32 an original stake P.282. Meas West to NW corner 4 104-15 5.45 (359.7').

6-1898 W. Fraser (P.633 No.572) set marked stake from bearing tree stump which brought it 5.45 East of NW corner 5.

1935 County Highway Department B.79, used corner post.

11-17-1993 County Surveyor dug for corner after finding N 4-5 104-15 W.F. measure 359.70 we dug looking for T. Hunter stake. We found a stake mark on South edge of post hole for angle iron post set in concrete for fence E-W-N. As we dug down the mark kept going. After we got to the bottom of the digging for the c.p. the mark was still there undisturbed. Clay was 2' deep. There was 18" of stake mark running vertically down running out at point. The stake mark is 1' South of South face of angle iron post. We dug from post 2' E 2' W and 4' South.

11-19-1993 County Surveyor set cast iron cap on telspar pipe in stake hole which is 1' South of angle iron CP bolted survey marker sign to angle iron CP.

3-24-2005 Massey Land Surveying Crew found cast iron cap on telspar pipe up 0.5' leaning east.

11-7-2005 County Surveyor found cast iron cap on telspar pipe up 0.4' bent to the east. Removed bent telspar pipe and set 5 1/2' telspar pipe w/cast iron cap up 0.2'.

3-4-2010 County survey crew found cast iron cap on telspar pipe at surface in good condition.