Certificate of Location of Government Corner

ID#: 600605 **Description:** W SEC COR 6 7 60 **Date Set:** 9/26/2003 **County:** Winona

Section: 06 **Township:** 106N **Range:** 10W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 9 1/2' south of centerline of E-W twp road, 2' west of fences north and south and 19 1/2' west of centerline of field drive south
Spike in CP S 28.90'
Post w/sign 12 1/2' south
This corner is located by GPS reference stations "Persons I & II"

Corner History:

1853 Gov't Notes: N 80.00 chains, set post in mound for corner, made mound and trench and deposited charred stake and hawthorn seeds.

7-1890 Thos Fraser (P.444 No.429 S.12) C.Carter and others (see also fd book 6 p.16-17 T.F. 1890) corner placed over 20 years before by a Mr. King in center of mound by old stake when road first graded up. Corner never found but often looked for. On digging a half day started to run in corner. On digging further east later while others seeking corners east, Mr. Carter found stake and small 10" triangular stone that Mr. Carter and Mr. Pringle had seen placed 20 odd years before. Wheel tracks compacting soil proved if correct placed 4x10x25 pointed with old stone below and stake by side "this was about 8' east of fence" likely fence south.

3-1980 Roger Brand set the 1/16 south, a 3/4" iron pipe with elbow on top. Falls 7' north of fence east and 1.0' west of N-S fence. E-W fence probably will be taken out soon (1321.67-1321.67). By line from SW 7 run W 1/4 cor 7 (as used this survey) corner could be 4' west where in corner form fence line.

3-18-1983 County Surveyor could not find 1/2" rod set in 1974, also dug 12' south to double over 1/16 cor (fence east) south of this sec cor did not find anything. Dug 3' diam and found area cut to clay. Be careful, 1/2" rod set 3-18-83 as traverse pt may still be in place appx 1.8' south of car jack tube set 1983 remon book for RP's to 1/2" rod.

3-20-1983 RWB survey in sec 7-106-11, set 18" piece of car jack tube as corner from traverse from west and checked from a traverse from SE from west and checked from a traverse from SE set at 1974 1/2" rod location. Ties: Spk in cor fe post south 28.90'. Spk in brace post SW 29.80'. S edge of sign post SSE 8.5'.

4-12-2000 County Surveyor found 1/2" rerod down 0.6' traverse point. Found no further evidence.

9-26-2003 County Surveyor set CIC on 4 1/2' telspar pipe down 0.3' from 2000 reference.

2-20-2009 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.