Certificate of Location of Government Corner

ID#: 610705 **Description:** W SEC COR 7 18 61 **Date Set:** 5/1/2007 **County:** Olmsted

Section: 07 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 5' west of centerline of N-S twp road and in centerline of E-W twp road
County Survey Disk in SE side PP #11 NE 52.39'
County Survey Disk in SE side stub TP SW 51.19'
This corner is located by GPS reference stations "FKN A & B"

Corner History:

9-1853 Gov't Notes - John Ball, Deputy Surveyor North between sections 13 amd 18. 80.00 chs. Set post and drove charred stake for corner to Sections 7, 12, 13, and 18. Built mound with trench per instructions. Planted Osage S.E. and N.E. Apple seed.

9-1853 Gov't Notes - William A. Jones, Deputy Surveyor West on true line between Sections 12 and 13. 40.18 1/2 chs. Set post at quarter section corner. 80.37 chs. To section corner.

10-1853 Gov't Notes - William A. Jones, Deputy Surveyor. East on true line between Sections 7 and 18. 39.58 chs. Set quarter section corner. 79.58 chs. To section corner.

9-1857 E.P. Bircher, Surveyor, by T. Hunter, Deputy, (Old Road Book, Road No. 101) surveyed road running North and South but makes no call for the corner here.

8-27-1874 Thomas Hunter, County Surveyor, (Book A, Page 257, No. 257) measured 79.96 chs. south to W. Sec. Cor. 18-19, a stake with stones on each side.

6-4-1875 T. Hunter (Book A, Page 281, No. 278 and old field book 4, page 62) "Found by digging in center of crossroads the remains of old stake. Set stone in its place 16x10x8 inches with old stake found by its side." Measured 39.91 1/2 chs. to the S 1/4 Cor. 12, a 19"x11"x5" boulder set in place of the stake found, then 39.94 chs. to Sec. Cor. 11-12-13-14, a stone 14x8x3 inches set in place of old stake found.

12-1890 Thomas Fraser, County Surveyor, (Book A, Page 450, No. 434 and old field book 7, Page 76) "found boulder stone 10x6x16 said to have been placed where original corner stood." Measured 79.87 1/2 chs. south to W. Sec. Cor. 18-19, a large stone 26x12x3. He set the 1/16 North of W. Sec. Cor. 18-19, a stake, on line and at proportional distance to W. Sec. Corn. 7-18 (W 1/4 Cor. 18 could not be found).

6-1900 Robert Fraser, Deputy County Surveyor, (Book A, Page 686, No. 610 and old field book 15, Page 89) "found a boulder stone in road as recorded in previous survey." He measured East 2 miles and over ran Gov't measure by 16 links. He set Sec. Cor. 7-8-17-18 (E-W) at proportionate Gov't measure. (Measure 79.66 chs. to Sec. Cor. 7-8-17-18, then 80.23 chs. Sec. Cor. 8-9-16-17.)

1952 John Kerr (Kerr Book 53, Page 70) "Dug hole 10'x14' by 5' deep. Found remains of boulder broken off. Placed 1"x39" iron pipe with piece of boulder on South side." Shows measure west of 5265.5.

9-11&17-1973 County Surveyor (Card) found Kerr's pipe leaning badly due to wet conditions. No references remaining. Dug entire area west and north of pipe. Conditions very wet and mucky. Could not even find stone found by Kerr. Also dug for 1/4 9-11&17-1973 Cor. 12-13 but could not find it.

7-11-1975 County Surveyor dug the S.W. quadrant of the intersection but found nothing.

9-19-1975 County Surveyor set a Cast Iron Monument as the corner at Hunter's measure from Sec. Cor. 11-12-13-14 and at Thomas Fraser's measure from W. Sec. Cor. 18-19.

4-1979 County Surveyor used this corner to reset the W. 1/4 Cor. 7 midway and on line to W. Sec. Cor. 6-7. Quarter corner came in line with fences East and West. Also set 1/4 Cor. 12-13 this survey after survey of N-S 1/4 line of Sec. 12 (surveyed by Hunter in 1875--Book A, Page 281, No. 278). Measured West to 1/4 Cor. 12-13 2635.03.

7-16-1980 County Surveyor found the Cast Iron Monument broken. Reset top piece of monument from references as temporary corner. Measured 5252.14 east to Sec. Cor. 7-8-17-18.

10-21-1983 County Surveyor found the Cast Iron Monument knocked over again. Removed monument and dug down to the re-rod beneath it. Drove a 4' telspar pipe with a Cast Iron Cap as the corner over the re-rod.

6-13-2002 County Surveyor found cast iron cap on telspar pipe down 0.1' bent and leaning and missing cast iron cap.

5-1-2007 County Surveyor found telspar pipe w/o cap at surface leaning NE. Removed telspar pipe and set 7' telspar pipe w/cast iron cap down 0.5' at computed position.