Certificate of Location of Government Corner

ID#: 611005 **Description:** SEC COR 9 10 15 16 61 **Date Set:** 6/17/2011 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls in centerline crack of CSAH 10
The monument is at the surface and in line with fence east.
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 15 and 16. 80.00 chs. Set post at corner to Sections 9-10-15-16. Made mound, trench, and pits planted Cherry seeds S.W. & N.W. Plum S.E. Bur Oak 12" S89&3/4° 1270 lks. Bur Oak 4" S 33½°W 23 lks.

9-1857 E.P. Bircher, Surveyor, per T. Hunter, Deputy, (Old Road Book, Road No. 24) surveyed the N-S road here. Measured 40.00 chs. north to ¼ Cor. 9-10 and 40.00 chs. south to % Cor. 15-16.

1925 County Highway Department (C.H.D. Book 36) surveyed the N-S road here but made no call for the corner. Road in slight curve (probably around curve on West side of road).

7-20-1885 Thomas Hunter, County Surveyor, (Book A. Page 400, No. 390) Section corner missing and tho we measured from B (¼ Cor. 10-15) to C (Sec. Cor. 9-10-15-16) and from E (S.W. Cor. 15) to C we failed to find any evidence of where it originally stood being in thick brush, so fixed corner." He measured 39.89 chs. north from ¼ Cor. 15-16, a stone 26" long, 4" thick, and 10" wide at bottom and running to a point on top and set in place of stake found, to the "line of fence running East in direction of CD (N.W. Cor. 15 to N. ¼ Cor. 15) which is claimed to have been set on line when corner was standing at C."

1944 County Highway Department (C.H.D. Book 168, 169, 171) surveyed the N-S road. Shows Sec. Cor. 9-10-15-16 on line from a pipe at ¼ Cor. 15-16 to a 60d spike at ¼ Cor. 9-10 but does not mention any monument for method for choosing location.

9-26-1983 Ronald Olson, Surveyor, set a 5/8" x 18" rod as corner in the centerline of CSAH 10 and at double the distance from ¼ Cor. 9-10 (as set this survey) to the E-W fence at the 1/16 south.

10-20-1983 County Surveyor removed 5/8" rod set by Ron Olson and set a 1" square pipe with cap (RLS 8952) in its place as the corner. After study of County Highway Department cross sections in this area we feel that the original corner and any set since would have been destroyed by road construction, the area at the rod being in the center of the west ditch section of the previous road. The corner as set holds the fences at the 1/16 North and the 1/16 South midway to the respective ¼ corners, and the fence at the 1/16 west within 2' of midway to ¼ Cor. 9-16.

3-7-2007 County Surveyor found 1" square pipe without cap down 0.2' in good condition. Set new cap.

6-17-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates.