Certificate of Location of Government Corner

ID#: 613304 **Description:** S 1/4 SEC COR 33 61 **Date Set:** 1/4/1983 **County:** Olmsted

Section: 33 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe with cap RLS #8952

Reference Ties:

The corner falls 0.25' south of centerline of CSAH 10
Punch hole in top E end CMP in field drive NW 51.63'
County Survey Disk in PP NE 102.97'
County Survey Disk in 2nd brace post SSW 61.81'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes, John Ball, Deputy Surveyor West between Section 4 and 33. 40.00 chs. Set post for quarter section corner and drove charred stake and built mound with trench per instructions. Planted S.E. plumb, N.E. appleseed.

10-1897 William Fraser, County Surveyor, (Book A, Page 612, No. 556) "Could not find corner so located it on line and midway(39.945 lks.) between A (N.E. Cor. 4) and C (N.W. Cor. 4)." He used this corner to set the Center 4, a stake driven well down with a stone by its side, at the intersection of the ¼ lines, and the 1/16 South of the Center 4, a limestone with boulder on either side, midway (19.77 chs.) and on line between the Center 4 and the S. ¼ Cor. 4.

6-1976 County Surveyor dug midway (2636.58) and on line between the section corners but did not find anything. We dug for the S. ¼ Cor. 4 and found the recorded boulder (Book A. Pg. 340, No. 334) leaning to the S.W. so we dug down and took the center of the black mark beneath the stone as the corner location. We also found Fraser's stones at the 1/16 North of the S. ¼ Cor. 4, but could not find his stake at the Center 4. The line projected from the S. ¼ Cor. 4 over the stone at the 1/16 North would fall 4'± East of the midway position at the N. ¼ Cor.; however, since the North line of Section 4 measures so close to Fraser's measure we accepted the midway location as more accurate perpetuation of Fraser's corner than the projected line. Set a ½" rod as the corner midway and on line between the section corners. The road here is to be graded.

5-19-1982 County Surveyor, after the road had been graded the County Surveyor set a 1" square pipe as the corner midway and on line between the section corners as the corner.

1-4-1983 County Surveyor set a 1" square pipe w/cap as the corner in new concrete on CR 10 midway and on line between the section corners as the corner.

7-23-2003 County Surveyor found 1" square pipe w/cap at surface in good condition. Fence line to the south is gone.