Certificate of Location of Government Corner

ID#: 620205 **Description:** SEC COR 2 3 10 11 62 **Date Set:** 5/11/1972 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1 1/2' north of centerline of E-W twp road and in line with N-S PP line
Bottle cap in NE side PP #38181 S 43°10' E, 46.17'
County Survey Disk in E side fence post N 0°49' E, 27.39' (leaning north)
MnDOT 4" Spike & Disc in East face of fence corner post - S 17°35' W, 48.15'
This corner is located by GPS measurement

Corner History:

Set by William Jones 9-1853. 80.00 Set post at corner to sections 2, 3, 10, 11 deposited handfull charcoal made moung trench and pits and planted cherry seeds SE & NW.

10-1872 T. Hunter Bk A. Pg. 209 Reset the corner with a stake by the recorded gov't meas.

6-1893 W. Fraser Bk. A. Pg. 511 Found the stake and set a stone. 1/16 west set stone 3x12x15 M & L 19.98 1/2)

3-31-1971 County Surveyor found 1" iron in center road in line N-S fence. Likely set in Sandstone survey of Section 10. Measure West from iron R 1319.01 to eyeball line of fence north. 1321.2 - eyeball line of fence south 1652.6 property line. Center pavement Hwy 42 and centerline road east 2637.8

5-9-1972 County Surveyor found the recorded limestone and drove an iron 1" by 10" by the stone.

5-11-1972 County Surveyor set CIM at stone location.

5-11-83 County Surveyor CSD E side fence post in ditch N 27.39'. Found measured west to 1/16 1316.97. Final measure south to 1/4 10-11 as set 2639.74

9-28-92 County Surveyor found CIM in good condition"1/16 ston" west set by W. Fraser 3x12x15 M & L 1319.0. Found stone easily over 3' deep - set 1 1/4 x 2' pipe as corner over stone andjunk - 1.5 L Centerline road 2.0' E fence north. 54.62 NE to pepsi cap on SE side PP# 38187. 34.05 N to Pepsi cap on E side new corner post of fences running N & W. 42.35 SE to Centerline end buried road culvert. Eyeball measure of property fence running south 1650.25 from CIM.

Note: Removed the iron which had been set in a previous survey.

6-11-2002 County Surveyor found CIM down 0.4' in good condition.

4-5-2007 County Surveyor found CIM down 0.4' in good condition.

10-28-2013 MnDOT Survey Crew found the Cast Iron Monument in good condition.

05-19-2014 MnDOT Survey Crew checked for and updated existing ties. Set 1 new tie: MnDOT 4" Spike & Disc in East face of fence corner post - S 17°35' W, 48.15'