Certificate of Location of Government Corner

ID#: 620804 **Description:** 1/4 SEC COR 8 17 62 **Date Set:** 7/30/2001 **County:** Olmsted

Section: 08 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' south of centerline of E-W twp road and 59' east of centerline of driveway south
County Survey Disk in PP WSW 83.56'
Punch hole in NW end 48" CMP NW 32.58'
This corner is located by GPS measurement

Corner History:

Set by William Jones 9-1853. West on true line. 39.98 1/2 Br. Oak 6N80E 410; Br. Oak 8S85W 520.

5-1877 T. Hunter P. 310 No. 304 -**found undisrupted stake in mound in slough. Measured North to stake for line east 15 chains then 17.00 chains to south RW of Railroad. Measured North to stake for lien West - 1/16 corner. Set marked stake M & L 19.80 to center sec. Stake.

5-31-1974 County Surveyor dug with tractor and found about 2' of old wood stake. This wood stake falls 1.47' North of the E-W section line. Measure E - 2633.93; W - 2638.90. Set a long iron rod prior to road grading.

Spring 1975 Thomas Taylor. Reset something back at corner as the new culvert completely destroyed it's location. They reset by elec. Meas and 1.97' North line between sec. corners.

6-23-83 County Surveyor found 3/4 re-rod but 2.2' too far East and ±.9' too far South of position indicated on card. Got no dip at all at indicated location. Did not have time to remeasure line precisely after discovering iron out of position. Left as found.

7-30-2001 County Surveyor set 4' telspar pipe w/Cast Iron Cap down 0.3' as final corner. Found 3/4" rerod and removed.

4-13-2009 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.