Certificate of Location of Government Corner

ID#: 620906 **Description:** 1/4 SEC COR 8 9 62 **Date Set:** 6/3/1974 **County:** Olmsted

Section: 09 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 41' south of centerline of TH 14 and 1 1/2' east of centerline of CR 102
R/W monument WNW 31.6'
County Survey Disk in SW side PP SE 50.54'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William Jones, Deputy Surveyor North between sections 8 and 9. 40.00 chs. Set post at quarter section corner. Made trench. Burr Oak 8 in. S5°W 520 lks.

5-1877 Thomas Hunter (P. 310 No. 304), County Surveyor, states corner gone, bearing trees gone, and no evidence or knowledge except that the fence east had been set on line when corner was there. Set a marked stake at 1/4 corner in center of road and in line with fence east.

5-1903 Charles Armstrong (P. 46 Book B); County Surveyor, found boulder stone with stones around it. (from cards: measure South 1/2 mile and North to E 1/4 5 each 1/2 mile 39.89 - used to set sec corner 4-5-8-9. Hunter survey P. 310 states "from 1/4 post at H South to Center of RR track is 14.63 chs. 965.58".)

1930's State Hwy Plans (R/W) shows 1/4 corner 42' S of centerline pavement TH 14.

6-3-1974 County Surveyor dug at corner location but found nothing. Reset the corner midway and on line at 2638.30' by electronic measure. Set a CIM over a 1/2" x 3' rod. (from cards: Dug out the W 1/2 of the road on the N side of the culvert. Found nothing. Reset the corner Midway and On line at 2638.30' by electronic measure. Set a CIM over a 1/2" x 3' rod. R.P.'s Corner falls in the East wheel track of the N-S township road. Nail centerline TH 14. North 41.22'. R/W monument (pipe & cap) ESE 31.6'. This location came very close to location shown on MHD TH 14 R/W map.

6-23-1983 Mn/DOT working in intersection but found CIM in place, down 1'+. New culvert just inches South but CIM seems to be standing OK and R.P's checked fairly close. RP: R/W Monument ESE 31.49'.

12-10-2001 V. Fangman set 1/2" pipe w/cap over CIM.

6-25-2008 Massey Land Surveying found and used 1/2" pipe over CIM as corner.

4-24-2009 County Suveyor found 1/2" pipe at surface in good condition. Removed 1/2" pipe and found CIM down 1' in good condition.