Certificate of Location of Government Corner

ID#: 621404 **Description:** 1/4 SEC COR 14 23 62 **Date Set:** 5/10/2000 **County:** Olmsted

Section: 14 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of twp road south and 1' north of centerline of Knowledge Road west
Plastic disc and nail in PP SE 46.82'
Bottom bolt of stop sign post SW 46.80'
This corner is located by GPS measurement

Corner History:

9-1853 1/4 Corner 14-23. Set by William Jones. 40.00 Set post at gr. Sec. corner Br. Oak 5S 8W 139 and dug trench

7-1871 T. Hunter P. 186 No. 197 Price found stake in road driven where settlers avered original stake stood. 1/16 west set staked M & L 19.94 marked for line N. & S. 1/16 south set stake M & L 19.93 temp. Measured north to center 14 39.87

8-1887 T. Hunter P. 421 No. 410 found stake P. 186 set stone in place of stake - No bearing trees. 1/16 east set stake 19.98 1/2 M & L Mr. Price and Mr. James will set stone later as 1/16 corner for line south.

7-1917 J. Kerr Book 10 P. 24-26. Found stone at 26 + 35.70 from S.W. 14 with Iron Stake on line between af 1317.85 Ties: 2 1/2' Cottonwood Tree SE - 39' 10" large Cor. Post - SW - 48.25'

8-9-1954 J. Kerr Book 59 P. 75 found L.S. with 1 1/4" pipe riser Spk in P.P. - NE - 32.35 Spud in treated fence post - WSW - 49.70 Spud in P.P. Guy - W.N.W. - 39.50
120 p. spk in Twin 18" Br. O. W.N.W. - 64.0

8-1961 J. Kerr found stone after elaborate digging. Set CIM over stone. Co. Hwy Dept regraded road east -- new references. Disc in corner fence post SW 49.75 Hub SE 98.97

8-15-1968 J. Kerr CIM too close to top removed long CIM set shorty in place 7" or 8" down

8-11-1969 J. Kerr head of CIM broken off removed set new shorty CIM. Co. Hwy Dept B 248 19.61± Meas. N. 2636.38 Meas. East 2640.83

8-8-1974 County Surveyor Road to be graded to south. Found CIM - 8" deep. Took additional R.P.
Co. Surv. Disc in loading shute post (most NEly post) S.E. 121.97' Power pole NE 58.11' - C.S.D. East side

6-23-1983 County Surveyor found C.I.M. down 12" in road. 1' west of Centerline on curve from south to NE and 30' North of center of field drive on west side of road. South. Rp's 3/4" re-rod 14' East of Centerline road south and 86.8' SSW of P.P. with Rp. SE 38.91'

4-28-2000 County Surveyor found CIM down 1.5' in good condition.

5-10-2000 County Surveyor set 1" square pipe w/cap over CIM.

6-16-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

11-25-2003 Mn/DOT survey crew found monument in good condition.

8-23-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-20-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.