Certificate of Location of Government Corner

ID#: 621505 **Description:** SEC COR 15 16 21 22 62 **Date Set:** 4/3/2009 **County:** Olmsted

Section: 15 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of E-W twp road and in centerline of N-S twp road
County Survey Disk in SE side PP SW 65.89'
60d spike in NE side 22" Pine SE 67.2' (grown over)
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes West between sections 15 and 22. 40.05 chs. Set post at quarter section corner. Deposited charred stake, made mound, trench, and pits and planted cherry seeds NW and SE. 9-1853 Set by William Jones 80.00 Set post at corner to sect. 15, 16, 21 & 22 Br. Oak 10 N 65 E 54 Br. Oak 8 N 74 W 118 Br Oak 9 S 54 W 174 Br Oak 5 S 51 E 113

11-1856 Thomas Hunter (P. 18 No. 29), County Surveyor, used corner to sub-divide section 22.
1/16 East 19.97 1/2 chs. M & L to 1/4 Post.

7-1892 Thos Fraser. P. 493 No. 467. Corner gone, relocated corner set stone boulder from witness tree N 65°E 54 links. Meas south 39.99 1/16 West set boulder M & L 19.97 1/2'

5-1896 T. Hunter P. 599 No. 544 Found stone center road. Tested NE Bt still standing. Meas. N-S sec line (W line 22). 79.98 chs

8-1898 W. Fraser P 640 No. 576 found corner set and located by Hunter (?)

8-7-1968 J. Kerr Meas only from rod set at 1/4 15-22 West 2632.0 found 1/16 fence south at 3944.6. Record 1856 only not reliable, set 120 or short rod in center N-S road - 4' south of north edge traveled surface of E-W road. At 5270.0 from CIM at SE corner 15. 35.2 NW to SW corner Cul abutment - 34.55 NE to SE corner culv abutment.

8-8-1968 County Surveyor Meas using 5' S of rod or near center crossroads as 00 found fence east at 2640.0 (very close)

8-31-1973 County Surveyor found short 1/2" rod set 8-7-1968 5270' from CIM over recorded stone at 14-15-22-23 due with backhoe found good sized boulder with pointed post up 3' deep 8"+ x 16"+ irregular shape. 2.1' west of rod or now 5272.1 4.8' S of rod set 1968 purposely 5' N of centerline. Set CIM over stone.

9-22-2006 Yaggy Colby Associates found CIM in good condition.

3-28-2008 Roger Brand & Associates used corner for survey in section 15.

4-3-2009 County Surveyor found CIM without head down 1' in good condition. Removed CIM and found 5/8" rerod down 2.5' in good condition. Removed rerod and found boulder stone down 3.4' in good condition. Set 3' telspar pipe w/Cast Iron Cap down 0.4' at CIM position.