Certificate of Location of Government Corner

ID#: 622704 **Description:** 1/4 SEC COR 27 34 62 **Date Set:** 6/1/2009 **County:** Olmsted

Section: 27 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.6'
The corner falls 4' north of centerline of E-W twp road and 43' east of centerline of residential driveway north
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes W.A. Jones, Deputy Surveyor, set post 39.82 chs. West of sec. corner Br Oak 12" N 88° E 430 lks. Br Oak 5" S 89° E 370 lks.

5-1856 Thos Hunter P.6 No.10 shows 1/4 post 1/16 west 19.94-1/2 M&L 2 BT's (N54-1/4°W 194 lks) and (S3-1/4°W 70-1/2 lks) meas north 39.76 chs to center sec.

4-1863 P.C. Compton P.68 No.96 shows 1/4 post. Set M&L between section corners.

5-1902 William Fraser, (P14B), County Surveyor, could not find corner. Set stone 6"x6"x8" midway and on line between SW corner sec 27 and SE corner sec 27. Also, set 1/16 stone east midway and on line.

6-1973 County Surveyor dug area of corner but found nothing. Found 1/16 corner east.

8-27-1974 County Surveyor reran the south line of section 27 and set the 1/4 corner at 1/3 of the west 3/4 of a mile using the SW corner sec 27 and 1/16 east of the 1/4 corner location for line.

11-21-1974 County Surveyor set CIM over a rod.

4-20-2009 County Surveyor found CIM down 1' in good condition.

5-19-2009 County Surveyor found CIM with head broken off down 1.3' in good condition.

6-1-2009 County Surveyor found CIM with head broken off down 1.3' in good condition. Removed CIM and found 1/2" rerod down 2.8' in good condition. Removed 1/2" rerod and set 6' telspar pipe w/Cast Iron Cap down 0.4' at CIM position.

9-21-2011 County survey crew found cast iron cap on telspar pipe down 0.1' in good condition. Lowered monument to 0.6' below the surface.