Certificate of Location of Government Corner

ID#: 623306 **Description:** 1/4 SEC COR 32 33 62 **Date Set:** 10/8/2008 **County:** Olmsted

Section: 33 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of centerline of CR 129 and in centerline of E-W twp road
Punch mark in lug S end 24" CMP WSW 69.89'
Punched cross in rivet N end 24" CMP WNW 67.82'
County Survey Disk in SW side PP #42598 NW 57.31'
This corner is located by GPS measurement

Corner History:

10-17-1853 Gov't Notes North between sections 32 and 33. Var. 10° 21' E. 39.00 enter timber Br. Oak openings bears NW and SE. 40.00 set post at gr. section corner. Br. Oak 10 S7.6W 57. Br. Oak 12 N65W 41. 60.00 leave timber NE.

8-1856 T. Hunter P.16 No.25 used corner. 1/16 east 20.07 (1324.62) M&L N89-1/2E line south. 1/16 south 19.89 (1312.74) M&L N3/4°W line east.

7-1939 J. Kerr P.488B town board found no trace of corner set nothing. Meas west line 33 2637.33 SW 33 to 1/4 28-29.

8-5-1968 J. Kerr set nail in center roads north, west and south. RP's: 44.7 to center number plate 15571 on power pole NW 46.0 to punched cross center iron beam headwall S end culvert SW.

6-4-1973 County Surveyor set 1/2" rod true M&L 2637.56 which came .23' west and .42' south of nail set 8-1968.

11-14-1994 T. Ferguson found and used 1/2" iron at this corner for survey in NE 1/4 section 32 106-12.

3-20-2001 Claassen Engineering found and used county iron.

5-11-2006 Land Consultants found and used 1/2" iron as corner for survey in SE 1/4 section 32 106-12.

10-8-2008 County Surveyor found RR spike down 0.7' in good condition, but did not match ties. Removed RR spike and found 1/2" rerod down 1.2' in good condition. Set 6' telspar pipe w/cast iron cap over 1/2" rerod down 0.5'.

4-15-2009 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.