Certificate of Location of Government Corner

ID#: 623604 **Description:** S 1/4 SEC COR 36 62 **Date Set:** 5/6/2009 **County:** Olmsted

Section: 36 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' north of centerline of E-W twp road and in line with fence south
County Survey Disk in E side 22" Cedar S 43.86'
County Survey Disk in SW side PP #12T NW 56.89'
This corner is located by GPS reference stations "Woodchuck A & B"

Corner History:

9-1853 Gov't Notes John Ball, Deputy Surveyor West between sections 36 and 1. 40.00 chs. Set post for quarter section corner. Burr Oak 6 in. N70E 57 lks. Burr Oak 10 in. S42 1/2E 154 lks.

1857 Thomas Hunter (P. 13 No. 20), County Surveyor, apparently used this corner to locate Center Section 1, Orion Township.

10-8-1975 County Surveyor dug north half of east-west road for 8' east and west of north-south fence line. Clean clay at 1'. Found nothing.

10-17-1975 County Surveyor set CIM over 1/2" x 18" rod as corner on line between SW corner Sec. 35 and SE corner Sec. 36 and in line with fences North and South. This location also fit line from N 1/4 corner Sec. 36 over fence at Center Sec. 36.

4-16-1981 County Surveyor found CIM ok, shot corner.

9-1-1988 County Surveyor found CIM gone from 1982 road grading only tie left was spike and CSD in 17" cedar. Reset CIM from (1975 trav points) tie to 17" cedar south changed to 43.50'.

4-27-2009 County Surveyor found CIM down 0.3' leaning NW.

4-28-2009 County Surveyor plumbed CIM. Took ties and removed. Found 1/2" rerod down 1.8' in good condition. Did not match ties. Set 60d spike down 0.2' at 1/2" rerod position. Will verify 1/2" rerod position before setting final monument.

5-6-2009 County Surveyor removed 60d spike and set 5' telspar pipe w/Cast Iron Cap down 0.4' at 1975 CIM position from GPS and traverse data.