Certificate of Location of Government Corner

ID#: 630105 **Description:** SEC COR 1 2 11 12 63 **Date Set:** 11/9/2006 **County:** Olmsted

Section: 01 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 3' south of centerline of E-W twp road, 37 1/2' west of centerline of creek culvert and 2' east of fence north
County Survey Disk in top of CP N'ly 34.52'
Spud in NW side PP #21416 SW 53.33'
County Survey Disk in PP #21416 SW 53.26'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: William A. Jones, Deputy Surveyor North between sections 11 and 12 80.00 set post corner to Section 1, 2, 11 and 12. 15" Bur Oak N 80° 30'E 883 links. 6" Bur Oak N 18° W 869 links. 5" Bur Oak S 2° W 860 links. 13" Bur Oak S 84° E 900 links

6-1885 Thomas Hunter, County Surveyor (Book 14 p. 41) at section corner 1,2,11 and 12 could not find corners. N.E. bearing tree still standing, but being so far away unreliable. Measurement from it would place corner too far west. Used corner post of fence running North as John and Mr. Whiting said it was set on line and 2 rods North of corner when standing. Measured South 10.47 chs. To R.R. stone.

12-1910 Charles Larson County Surveyor (Book 2 p. 142) at section corner 1, 2, 11 and 12 set iron stake, measured South to R.R. 696'.

9-1951 John Kerr County Surveyor (Book 52 p. 57) found iron stake at section corner 1, 2, 11 and 12 measured South to center line of R.R. 694.0.

10-1-1957 John Kerr County Surveyor (Book 67 p. 48) shows 3/4" pipe at section corner 1,2,11 and 12.

6-5-1962 John Kerr County Surveyor (Book 85 p. 45) shows iron at section corner 1,2,11 and 12.

10-12-1963 John Kerr County Surveyor set a C.I.M. at section corner 1,2,11 and 12 in location of 3/4" iron rod.

6-30-1982 County Surveyor dug west of John Kerr's C.I.M. found 5/8" x 15" re-rod down 6" 1.32' south and 0.62 west, found 3/4" x 30" re-rod 3.3' deep under C.I.M., also found 1" x 14" pointed iron 4.5' deep. At ± 6' deep there was a third road dug to 10' deep it was still 1' to natural soil.

6-16-1987 County Surveyor set C.I.M. over 1/2" rod at location of 1" iron found 1982.

9-22-2006 County Surveyor found CIM down 1.3' in good condition.

11-9-2006 County Surveyor set 1" square pipe w/cap at surface over CIM.