Certificate of Location of Government Corner

ID#: 630904 **Description:** 1/4 SEC COR 9 16 63 **Date Set:** 1/10/2006 **County:** Olmsted

Section: 09 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.7'
The corner falls 14' SE of centerline of CR 143 on curve, in line with centerline of CR 143 west and 30 1/2' west of centerline of CR 143 north
16d spike in 18" Oak S 63.52'
Cross in S end CMP SE 12.48'
County Survey Disk in PP SSE 32.91'
This corner is located by GPS reference stations "Slopes A & B"

Corner History:

1853 Gov't Notes, William Jones; 39.90 set 1/4 section post to corner. RPs- 10" burr oak N 2 1/2 W61, 8" burr oak S 83 W 6.

5-1874 Hunter, Pg.243 No.244; Found NE bearing tree and old stake. Set stone 4x8x15. 16 south set stone, 16 center NW 1/4 16 set stake.

4-1875 Hunter, Pg.267 No.265; Found stone pg.243. 16 east marked stake, 16 center SE 1/4 9 set stake.

1927 J. Kerr Bk.3 Pf.38 Camp Kahler; Found corner stone.

1956 J. Kerr shows limestone with original bearing tree, 16" burr oak 4' west removed when graded. 16d put on west side 18" burr oak SSE 63.52. Set 1/16 west with rod.

8-20-1963 J. Kerr set CIM over pipe. RPs-16d spike in 18" Oak South 63.52 ft. + in North end of corregated metal culvert N. of W. 350.6 ft., Spud in end fence post N.W. 44.31 ft.

5-1965 J. Kerr removed C.I.M. for road grading.

10-1969 J. Kerr corner now comes over culvert. Set RR spike.

1974 County Surveyor dug up RR spike. Left as is.

1984 Sandy Slopes Second Subdivision Plat shows RR spike.

1989 County Surveyor found nothing at corner-shot sandy slope 2nd corner to replace but did not set yet.

1-10-2006 County Surveyor set 1" square pipe w/cap at surface from GPS and traverse data.

4-17-2012 County survey crew found 1" square pipe with cap RLS 15809 at surface in good condition. Lowered pipe in preparation for bituminous road overlay.