Certificate of Location of Government Corner

ID#: 631005 **Description:** SEC COR 9 10 15 16 63 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.7'
The corner falls 1/2' east of centerline of CSAH 11 and in line with centerline of CR 143
County highway disk in SE side of power pole #45863 SW 47.82'
Reference pipe NW 37.75'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 80.0 set post at corner to section 9-10-15-16 and made trench. RPs- 8" red oak N64 E37, 8" red oak S 70 E 101, 6" burr oak S8 1/2 W 160.

4-1875 T. Hunter Pg.267 No.265; found original corner standing with trench still in place. 16 north set staek, 16 west set stake, 16 center SE 1/4 9 set stake.

9-1951 Bk.20 Pg.60 J.Kerr; set 1" pipe in post hole filled with rock & broken glass.

1968 J. Kerr, RPs- Spike & disc in 10" oak W 65.73, spike & disc in 12" Maple NW 90.61.

8-1969 J. Kerr reset CIM by county highway department after grading. RPs-Spike in T.P. North N.E. 92.2 ft, Spike in T.P. East N.E. 76.3 ft, disc in SE side pp SW 47.91.

5-1989 County Surveyor found CIM with broken head. Checked tie to PP #45863 SW 47.82. (1969 47.91).

6-22-1994 County highway crew found CIM with top broken off. Set reference point, 1" square pipe w/cap south edge gravel driveway to west side CR 11. Removed CIM before cold recycling bituminous surface of CR 11.

11-14-1994 County Highway Department set 1" square pipe w/cap at surface from 1994 overlay tie out.

12-15-2003 County survey crew found 1" square pipe w/broken cap at surface in good condition. Replaced broken cap.

6-23-2008 County survey crew found 1" square pipe w/cap at surface in good condition.

3-7-2012 County survey crew found 1" square pipe with cap at the surface in good condition. Lowered pipe and cap in preparation for bituminous road overlay.