Certificate of Location of Government Corner

ID#: 631104 **Description:** 1/4 SEC COR 11 14 63 **Date Set:** 7/29/2004 **County:** Olmsted

Section: 11 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 14 1/2' south of centerline of 19th St SE on curve, 33' east of centerline of Whispering Ln SE south and 2' west of tree line fence north
County Survey Disk in E side 24" base to twin Burr Oak NNE 61.04'
Spud in NE side PP #16224 (up 2') SE 38.32'
County Survey Disk in PP #16224 SE 38.34'
Punch hole in E end 30" CMP SW 23.07'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: William A. Jones, Deputy Surveyor West on true line between sections 11 and 14. 39.97 chs. Set post at quarter section corner. Bur Oak 8 in. N62°W 202 lks. Bur Oak 7 in. S42°E 53 lks. 79.94 chs. To seciton corner.

9-5&6-1856 E.P. Bircher, Surveyor, and T. Hunter, Deputy, (Old Road Book Road No. 35) surveyed a road on the N-S 1/4 line of section 11 and 14.

9-1873 Thomas Hunter, County Surveyor, (Old Field Book 2, Pages 27 and 28) did acreage survey for Healy in sections 11 and 14.

1-1879 Hunter, County Surveyor, (Old Field Book 5, Page 91) "found fence post braced for wire fence. Brace on N. side of post, and found stump of N.W. B.T. with blaze plain. Tested post and found it 2 links South of bearing and 2 links west of measurement from stump of B.T. according to field notes."

1-30&31-1882 Hunter (Book A, Page 372, No. 363) refers to survey for Healy in section 11 and 14 in 1873.

6-1898 William Fraser, County Surveyor, (Book A, Page 631, No. 571 and Old Field Book 9, Pages 1-3) "Found corner as given by T. Hunter in his field book but not recorded when he said that the stake stood 2 links East and 2 links North of the corner post of fence. We found bottom of old post between two posts now standing and stake as given above. Set new stake not marked." Set a stake at the 1/16 East midway (20 chains) and on line.

12-1941 John Kerr, County Surveyor, (Kerr Book 26, Pages 60-62) used this corner (no description) to set sec. Cor. 10-11-14-15.

6-1962 John Kerr (Kerr Book 85, Page 47 and Cert. Filed) "found a portion of stake and bark in hole in sand 2 1/2' below top of ground with various pieces of iron, bolts, spikes, chain, washers in spot 4" in diameter. Set CIM." Measured East 2636.35.

1-10-1980 County Surveyor found Kerr's C.I.M. standing but the head was broken off. Broke off the 1st section and set a 16" C.I.M. over the remainder. RPs-Corner 1' South of line of fence West, 11' North of centerline road East and 2' West of tree line with fence North, C.S. Disc in East 24" base to twin Bur Oak NNE 60.96, Spud in NE side P.P.# 16224 (up 2') SE 38.40, C.S. Disc West side 8" post (up 3 1/2') in fence line South S29.49.

10-26-1988 County Surveyor tied out corner for road grading (removed CIM)

3-26-1999 County Surveyor found remainder of Kerr's CIM down 1.7' in good condition

7-29-2004 County Surveyor found broken CIM down 1.7' in good condition. Removed CIM and found 1/2" rerod down 3' in good condition. Removed 1/2" rerod and set 7' telspar pipe w/cast iron cap down 0.4'.