Certificate of Location of Government Corner

ID#: 632105 **Description:** SEC COR 20 21 28 29 63 **Date Set:** 7/18/1978 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 32' east of centerline of CR 101
Punched cross in E end 36" CMP SSW 40.64'
Punched cross in W end 36" CMP SW 63.94'
Post w/sign 2' east
This corner is located by GPS reference stations "Whipple A & B"

Corner History:

10-1853 Gov't Notes: William A. Jones, Deputy Surveyor North between sections 28 and 29. 80.00 chs. Set post at corner to sections 20,21,28,&29. Deposited charcoal and made mound, pits, and trench. Planted cherry seeds S.E., S.W., N.E. & N.W.

5-1859 Thomas Hunter, County Surveyor, (Book A P. 60 No. 86) used the corner to set the 1/16th West midway (20.02 chs.) and on line and the 1/16th South midway (20.00 chs.) and on line.

5-1872 Thomas Hunter, County Surveyor, (Book A P. 198 No. 208) found a boulder set as the corner in a previous survey. Measured 39.78 chs. East to 1/4 Cor. 21-28 and 39.76 chs. From 1/4 Cor. 21-28 to Sec. Cor. 21-22-27-28.

10-1941 A. Armstrong (Armstrong Book 3 P. 53) measured from Sec. Cor. 21-22-27-28 to the corner post at 1/4 Cor. 21-28 and found the measure to agree exactly with Hunter's 1872 measure. He measured from the corner post at 1/4 Cor. 21-28 to the corner post at 1/4 Cor. 20-29 and found the measure just .2 shorter than the sum of Hunter's 1859 and 1872 measures. He measured North from the corner post at 1/4 Cor. 28-29 and found the 1/16th fence at 1320. He set an 8" x 10" x 30" limestone as Sec. Cor. 20-21-28-29 at 2640 North of the corner post at 1/4 Cor. 28-29 and at Hunter's prorated location (using measurements from Survey No. 86 and Survey No. 208) from the corner post at 1/4 Cor. 21-28 to the corner post at 1/4 Cor. 20-29.

5-27-1965 John Kerr (Certificate filed) found a large stone near the fence corner of fences North and East. Set a C.I.M. over a pipe as the corner with the stone alongside. RPs-disc in corner fence post N 0.97(gone), disc in 12" box elder NE 15.4(gone), disc in telephone pole SW 15.0(gone), punched cross top of east eand 36" road galv. Culvert SSW 40.62'.

7-18-1978 County Surveyor found Kerr's C.I.M. broken and removed it. Found a 1/2" rod beneath the C.I.M Reset a new C.I.M. over the rod and took reference points. RPs- stone on east side corner 33' E center of road, punched cross east end 36" culv SSW 40.62', punched cross west end 36" culv W 63.83'.

6-1989 County Surveyor found CIM at surface in ditch & brushy area. Monument is near N-S-E fence intersection. Retook old ties-punch cross east end 36" culvert SSW 63.94', post & sign 3.0' east.

8-3-2005 County Surveyor found CIM down 0.1' in good condition.