Certificate of Location of Government Corner

ID#: 632205 **Description:** SEC COR 21 22 27 28 63 **Date Set:** 8/5/2005 **County:** Olmsted

Section: 22 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 11' east of centerline of CSAH 36
Iron rod east of large Oak W 74.6'
County Survey Disk in N side PP #41442 E 61.09'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 80.0 set post at corner to section 21-22-27-28. RPs- 12" burr oak N58 E 512, 14" burr oak N50 W 81, 9" burr oak S55 W 62, 11" burr oak S 43 1/2 E 52 1/2.

5-1872 T. Hunter Pg.198 No.20; Found stone and accepted as found. Witness trees NW & SE standing seemed 5 links too far north for SEBT, 5 links too far south for NWBT. Trees near straight line over corner. 9 links off record.

6-1892 T.Fraser Pg.492 No.466; Found stone Pg.198. 16 south set limestone.

1930 J.Kerr Bk.3 Pg.35-39; Found limestone.

1941 A. Armstong; Found stone in centerline road from ties- spike in oak W 74.6', spike in oak SW 41.0'.

1946 J. Kerr found corner destroyed. Reset 3/4" pipe with 1/2" rod riser.

9-21-1963 J. Kerr set CIM with 1/2" rod below. RPs- spike in oak SW 41.0', spike in oak W 74.6', spike in fence post NE 43.6', spike in fence post SE 59.45', spike in fence post W 35.32'. (Ties all gone in 4-1972, R.B.)

6-24-1970 County Surveyor removed C.I.M. for grading. Set 1/2"x2' rod over original rod below CIM. RPs- CIM set by state as RW marker E 89.44', iron rod just east of large oak W 74.6. Set 5/8" x20' rod on line from CIM to edge conc. Blocks on south edge window opening or 6.55' north of conc. Edge window at 136.0' then 106.75' to conc. Edge by window. Angle setting on section corner from CIM as ERW. E by N to window edge 141°34'.

4-18-1972 County Surveyor reset C.I.M. RPs- Corner comes on E edge blacktop, Set 1/2"x18" rod below, all ties to house inplace, 89.44' E to CIM type R/W monument, 91.0' west, transit line from E R/W monu. Over corner reset falls 1.12' north of west R/W monu.

1-24-1989 County Surveyor found CIM with broken head, centerline CR #36 west 11.2', CSD in transmission pole east 61.09'.

8-3-2005 County Surveyor found CIM with head broken down 0.2' took local ties and removed. Found 1/2" rod down 2.7' took local ties.

8-5-2005 County Surveyor set 1" square pipe w/cap at surface from local ties taken from 1/2" rod. CSD with nail in north side of PP #41442 east 61.09'. Did not look for iron rod by Oak and CIM R/W monument gone.

4-3-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.

9-8-2016 County survey crew found the 1" square pipe in good condition although the aluminum cap was broken. Lowered the monument 0.4' in preparation for bituminous mill and overlay project.