Certificate of Location of Government Corner

ID#: 632504 **Description:** 1/4 SEC COR 25 36 63 **Date Set:** 2/2/2012 **County:** Olmsted

Section: 25 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

120d spike falls 1/2' north of E-W fence and 4' east of fence north
1/2" rerod falls 1' south of E-W fence and 4' east of fence north
Post w/sign in E-W fence
This corner is located by GPS reference stations "Blake A & B"

Corner History:

1853 Gov't Notes, William jones; 40.0 set a 1/4 section post. Deposited charcoal, made mound, trench, pits, and planted cherry seeds NE & SW.

4-12-1899 W. Fraser page 475 No. 454 (Caption) set small stone midway between section corners

4-1892 T.Fraser Pg.475 No.454; Corner gone. Set temp point.

1935 county highway department Bk.87 Pg.71; Found flat limestone. Set hub at 1/16 corner east. NW corner 36 found boulder with cross with stakes on east side of stone. PRs- tele pole SE 89.0, fence post SW 43.0. NE corner 36 found limestone with 4x12 bottom. RPs- tele pole NW 25.0, gale post NE 65.0, corner fence post S30.5.

7-1965 J.Kerr; Found NE 36 meas west on fence line set 120D at 1320 in line fence west which came 5' out in road surface from west side road. Found easily once but couldn't find 6-27-1969. Found main fence north and set 120D to hold meas. Set 120D later at 2636.15 or midway. Also set 120D at3954.2 from NE 36 with hub under fence E-W which came about 7' east of fence running north which was at station 3961. Same propartion overrun as fence north at N 1/4 36. Set CIM from old witness stone straight west of NW 36 making certain of meas of 5272.3 total mile.

6-1969 J. Kerr found 120D under fence. Dug 18" round deep hole just east of nail set. 5 limestones on end east of nail. Filled hole. RP- hard nail in new cedar corner post for terminal corner of new steel fence running west; first steel post center 28.71' west hard nail 4.1' to 120 which may move some. E-W line must be run. Used 120 to set center 36 so must be preserved.

10-14-2003 Massey Land Surveying found and used 1/2" rerod.

11-3-2006 County Surveyor found 120d spike with stones on east side down 0.5' in good condition. Also found 1/2" rerod down 0.2' in good condition 1.40' south of the 120d spike. The origin of the 1/2" rerod is unknown and it was decided the 120d spike marks the location of the quarter corner.

2-2-2012 County survey crew found 120d spike in good condition. Removed and replaced with a 5' telspar pipe with cast iron cap. Also found 1/2" rerod 1.40 south and removed.