Certificate of Location of Government Corner

ID#: 632705 **Description:** SEC COR 27 28 33 34 63 **Date Set:** 10/23/2000 **County:** Olmsted

Section: 27 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' east of centerline of CR 111 and 19' north of centerline of farm drive east
County Survey Disk in S side PP #45086 NE 64.08'
1/2" rod in pasture on line to very top of silo WNW 171.65'
1/2" rod in pasture on line to NW corner of barn foundation SW 218.83'
Ref pipe SE 50.04'
This corner is located by GPS measurement

Corner History:

10-1853 Governemnt Notes, William A. Jones, Deputy Surveyor; North between section 33 & 34. 80.00chs. Set stone 15x12x4" at corner sections 27-28-33-34. Reference points: Burr Oak 12" S45 1/2 °E 184 lks. Burr Oak 14" S6 °W 327 lks. Burr Oak 10" N3 1/2 °W 555 lks.

5 thru 11-1872 Thomas Hunter, County Surveyor, (Bk A, Pg 198, No. 208, Old Fieldbook 2, Pg 10 and Old Fieldbook 1, Pg 15) "section corner missing. Found stumps witness trees with marks plain and reset it from them by US Field Notes, the distances agreeing very closely but the bearings not very close. Reset it at point indicated by measurements, and properly marked stake as section corner." He used the corner to set the 1/16 south, a stake midway (19.94 chs) and on line and the 1/16 north, a stake midway (19.83 chs) and on line.

6-1876 T.Hunter (Bk A, Pg 297, No. 292 and Old Fieldbook 4, Pg 128) "found stake properly marked as set in survey No. 208, pg 198 from U.S. Field Notes." He also found the stake set P. 198 at the 1/16 South. He doubled the line and measure (19.96 1/2 chs) from section corner 27-28-33-34 over the 1/16 south to reset 1/4 corner 33-34.

6-1930 John Kerr, County Surveyor, (Kerr Bk 3, Pg 35) set corner (no description) by doubling measure (2636.3) from the NE corner section 34 over "N 1/4 line" and prorating according to Hunter's old measurement; I.e. he used 39.66 (1872 Hunter) North to 1/4 corner 27-28 and 39.93 (1876 hunter) South twice to South section corner 33-34 (point used here not described). Measured 5274.9 west to section corner 28-29-32-33 (no description), 2619.16 North to 1/4 corner 27-28 and South 5273.94 to South section corner 33-34.

1932 County Highway Department (C.H.D. Bk 71, Pg 4) "stone monument found, 4"x6"x18" limestone in place." Topo here shows C.H.D. Corner 3' North of farmyard fence East. Measured South 2637.8 to stone found at 1/4 corner 33-34.

6-13-1969 J.Kerr (Kerr Bk 101, Pg 34-35-36) apparently doubled line and measure (1317.95) from 1/4 corner 33-34 (found this survey) over a stone found at the 1/16 North and set a C.I.M. as this corner which came in 12' of fill in road. He also set a 1/2" iron at the 1/16 North midway (1306.87) and on line.

9-20-1976 County Surveyor took references to Kerr's C.I.M. before road graded. RPs- 1/2"x2' rod in pasture on line to very top of silo WNW 171.65, 1/2"x2' rod in pasture on line to NW corner of barn foundation SW 218.83.

8-26-1980 County Surveyor set a C.I.M. over a 5/8"x15" iron from references taken. This corner filled over many feet.

5-22-2000 County Surveyor found CIM down 1.5' in good condition. Set ref pipe and tied out corner.

10-23-2000 County Surveyor set 1" square pipe w/cap at surface from 2000 tie out.

8-16-2005 County Surveyor found 1" square pipe w/cap at surface in good condition.