Certificate of Location of Government Corner

ID#: 633606 **Description:** 1/4 SEC 35 36 63 **Date Set:** 4/30/1976 **County:** Olmsted

Section: 36 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1 1/2' east of centerline of N-S twp road and in line with fence east
County Survey Disk in W side PP NW 91.7'
County Survey Disk in E side PP #15417 SW 160.25'
1/2" pipe E 33.0'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.0 set quarter section post and deposited charcoal, mad moune, trench with pits, and planted cherry seeds NE & SW.

6-1877 T.Hunter Pg.318 No.312; Used corner (stone monument) to meas. North 2 1/2 miles 13, 157.76' to test NW corner 25 a stake found. Came within .26 of correct porportion.

4-1892 T.Fraser Pg.475 No.454; Town of Predmore laid out. Found long stone which was placed at early day when town of Marion was laid out.

1929 J.Kerr, Bk.1 Pg.25; found stone, meas. South 2637.0 to SW 36. Quote" Pg.25 found E 1/4 of sec. 35 and chained south and placed stake at 1320 and continued south to section corner of 35-36-1-2 a distance of 2637.0 and found boulders and stake. Replaced stake with one of red cedar marked section corner 1-2-35-36. Also placed drag tooth by side of cedar stake. Set stake M & L north at 1318.5. RPs- 8" white oak S29°E 89.0', 2' black oak S7°45'W 114.0'.

1938 county highway department Bk.96 Pg.4; Dug up 1x1x10" boulder. RPs- corner post E 27.3', tele pole NE 35.2', corner post SW 135.5', 1' below surface.

10-1963 J.Kerr removed large heavy dolomite stone. Placed in fence row east on east edge road ditch. RPs- spike in pp NW 95.4, iron under fence east 60.0, disc in tele pole NE 42.23.

12-1965 county highway department BK.97 Pg.8, found CIM. RPs- spike & disc in corner post E 33.64, spike & disc in tele pole NE 42.23', 2nd steel fence post south from corner post E SE 45.55'.

4-30-1976 County Surveyor found CIM. Set 10" CIM over. Corner in centerline N-S road and in line of fence east. RPs- CSD W side PP #15417 SW 160.25, CSD W side pp NW 91.7, property corner, pipe with cap #1613 on SW side of corner post E 33.0. Old RPs gone and didn't check for rod east.

5-7-1982 County Surveyor; PK nail in centerline newer bit. Surface road. Checked ties and found PK to be ok. Measured south to check Kerr's 1929 meas.

9-16-2003 County Surveyor found CIM down 0.4' in good condition.

10-14-2004 County Surveyor found CIM down 0.2' in good condition.