Certificate of Location of Government Corner

ID#: 640404 **Description:** 1/4 SEC COR 4 9 64 **Date Set:** 9/10/1998 **County:** Olmsted

Section: 04 **Township:** 106N **Range:** 14W **Monument Description:** 5/8" Copper Plug w/punch mark

Reference Ties:

The corner falls in centerline of CSAH 22 and 17' south of centerline of driveway west
County Survey Disk in N side PP #Q4021 SE 116.50'
County Survey Disk in N side PP #09967 W 94.04'
County Survey Disk in N side PP #24093 E 101.45'
This corner is located by GPS measurement

Corner History:

Gov't. Notes W.B. Kerby East Random 4&9, 40.00 set temp. section post west between 4&9 bar 9deg. 8'E. 40.00 set section post in mound, earth & soil, deposited charcoal, made trench and pitts, and planted Osage Orange seeds.

7-1857 T. Hunter Pg. 34, No. 55 shows 1/4 post, prop. Cor. West 5.48 then 16.85 to prop. Cor. Then 17.50 to cen. Sec. 1/16 east 19.77 M&L.

10-1892 W. Fraser P. 495 No. 468 S 3-4, Dorsey & Waldron found stake, set stone 2x5x12 in its place. 16 West stake M&L 19.95, meas. North from above 1/16 to inter. E-W 1/4 line 39.66.

12-1893 W. Fraser P.539 No. 500 S9, Cornflith, Stoppel found stone P.495 No. meas.

4-1897 W. Fraser P.606 No.551 SW1/4 S4, Stoppel found stone P.495. 16 west stake M&L 19.95.

5-1926 County Highway Department B45 P.27 - found 1/16 corner west in place.

12-1952 McGhie - 1/2" rod over 3/4" pipe. RPs- spike in pp N 105.40, centerline north end 24" culvert NE 31.4, centerline south end 24" culvert SE 30.0, SE corner stone machine shed NE 276.9.

7-1-1969 Co. Hwy. Dept. - 1/2" rod in place. RPs- spike in disc in pp NE 105.32, spike and disc in corner fence post NW 45.16.

7-1-1974 Co. Hwy. Dept. RPs- spike in disc in pp NE 88.98, spike in disc pp SE 113.2, spike in disc in pp WNW 88.18, transit line on line to pp 107.4 west of corner, also 2x2 hubs transit ties W 79.8 west.

7-21-1976 County Surveyor found rod over another rod over J.K.'s 5' pipe 5' deep. Found W.F. 2"x5"x12" limestone. Put rod on west side of stone. Set CIM over 5/8"x20" rod over stone. county highway department disc north side pp W 88.3, county highway department disc NE side pp SE 116.63, county highway department disc NW side pp
NE 86.10, punch hole top south end of 40" CMP E 57.19.

4-3-1978 County Surveyor set 16" CIM over CIM in place. Reference points OK.

7-24-1989 County Surveyor found CIM flush with CR#122 in centerline.

5-22-1997 County Surveyor found CIM in good condition. Tied out corner for construction. Set 1" square pipe/cap in north edge of res. Drive east
as ref. Pipe. 9' north of centerline driveway and 96' east of centerline CSAH# 22.

6-1997 This corner was destroyed in construction of CSAH 22 (West Circle Drive).

7-15-1998 County Surveyor drilled hole in concrete left turn lane of CSAH 22.

9-10-1998 County Surveyor set copper plug in drill hole.

2-7-2002 County Surveyor found copper plug in good condition.

6-9-2006 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.