Certificate of Location of Government Corner

ID#: 642405 **Description:** SEC COR 23 24 25 26 64 **Date Set:** 8/29/2007 **County:** Olmsted

Section: 24 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of 40th St SE and in centerline of St. Bridget Rd SE
County Survey Disk in SW side PP #30853 NW 77.93'
This corner is located by GPS reference stations "TSC A & B"

Corner History:

Gov't Notes - 80.00 set a section post in mound of earth, deposited charcoal, made trench & pitts, planted osage orange seeds NE & SW of trench.

5-1874 T. Hunter P. 250 No. 251 found stake. Replaced stake. Measure west 39.86 to stone set M&L.

4-1890 T. Fraser P. 438, No. 426 corner gone. Measure NE23 to SE26 39.851/2 = 2630.45
4 times.

5-1895 W. Fraser P.566 No.519 found mound (P.250) set stake & dug in small stones around stake. Measure north 39.84 (4-1890 39.851/2).

10-1901 W. Fraser, (Caption) found mound with stake & stones. 16 east set stake M&L 19.82.

12-12-1967 J. Kerr set CIM in place pipe & limestone. Corner 1000 ± east of US63 under fence marked drove rods on section line between US 63 & 1/4 23-26. One likely on W RW line.

8-4-1989 County Surveyor found CIM, set sign and post 1.0' south.

8-2-2000 Mn/DOT found CIM.

10-6-2000 County Surveyor found CIM up 0.2' leaning south 0.5' +/-

10-13-2000 County Surveyor found CIM leaning. Dug out monument and set cast iron cap on telspar pipe as corner.

3-4-2002 Mn/DOT survey crew found monument in good condition.

10-9-2002 County Surveyor found cast iron cap on telspar pipe at surface in good condition.

8-16-2005 County Surveyor visited area of corner. Found nothing. Corner destroyed by Hwy 63 construction.

8-29-2007 County Surveyor set 1" square pipe w/cap at surface from GPS and traverse data.