Certificate of Location of Government Corner

ID#: 642506 **Description:** 1/4 SEC COR 25 26 64 **Date Set:** 12/12/2006 **County:** Olmsted

Section: 25 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 101 and in centerline of CSAH 20
County Survey Disk in E side PP SW 79.62'
County Survey Disk in NE side PP SE 103.29'
This corner is located by GPS reference stations "B-32 & D-32"

Corner History:

1854 Gov't Notes - Yerby, 40.00 set a section post in mound of earth & soil. Made trench and pits. Deposited charcoal, planted osage orange seed E&W of trench.

10-1857 T. Hunter, Pg. 38 No. 60, Measure west 39.53 chains to center sec. 26, 1/16 south 19.871/2 chains M&L to section corner, Bearing tree's to 1/16 corner - N 893/4°W 258 lks.

4-1890 T. Fraser, P. 438, No. 426 corner long gone. Conway avers surveyors looked for it 20 years before and found nothing. Measure NE to SE 26 and took 1/4 total distance from SE 26. 39.851/2 (2630.43) set only point for N-S for 1/4 line west only temp point.

1945 county highway department Sta. 247+36.1. 35° 40' going north PI lies 21.1 north of 1/4 corner. Measure w1/4 25 to SW 25-2635.0.

10-16-1962 county highway department, Found boulder with X on top, stake on west side of stone. RPs-Spike & disc tele pole WSW 34.0'
Spike & disc in pp ENE 63.1'. Spike & disc in tele pole NE 67.2'.

11-26-1964 J Kerr set permanent CIM. Found 4x6x12 stone and pipe riser. Lines fence west across blacktop road lines, center road east and blacktop south beyond curve. Corner lies 60-70' ± east of centerline blacktop on curve. RPs-Spike tele pole NE 62.97. Disc wood stub tele cable marker SE 44.26, Center CR 20 West 69.5.

6-19-1974 County Surveyor reset a 5/8"x18" rod at corner location - water 6" from surface. Set no CIM. county highway department tore out former CIM.

7-3-1974 County Surveyor reset same iron a little west and north - note Rp's.

8-2-1989 County Surveyor found 3/4" rod in centerline of C.R. #101.

8-2-2000 Mn/DOT found 3/4" iron in good condition 0.7' deep.

10-4-2000 County Surveyor found 3/4" iron down 0.7' in good condition.

3-5-2002 Mn/DOT survey crew found 3/4" iron down 0.8' in good condition.

3-12-2003 County Surveyor did not find 3/4" iron rod, presumed destroyed by underground utility work done at intersection. Reset concrete nail from reference ties and turned angle from GPS points set to determine final location.

2-23-2004 County Surveyor set concrete nail at surface of CR 101 from angle from pt. A-32 & B-32. Set pt. C-32 to turn in concrete nail because A-32 will be destroyed by T.H. 52 improvement.

12-12-2006 County Surveyor set 1" square pipe w/cap RLS #15809 at surface from computed coordinates. CSD w/concrete nail in E side of PP no # SW 79.62' & CSD w/concrete nail in NE side of PP no # SE 103.29'.