Certificate of Location of Government Corner

ID#: 642606 **Description:** 1/4 SEC COR 26 27 64 **Date Set:** 10/6/89 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in 16" Boxelder NW 7.64'
Post w/sign 1' north
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby, 40.00 set a section post. RPs-Burr Oak 10 S1/2E 30 lks. Burr Oak 12 S1103/4 W 21/2 lks.

10-1857 T. Hunter Pg. 38 No. 60 Shows 1/4 post. Measure east 39.77 chains to center section, 1/16 south 19.92 chains M&L to section corner.

5-1875 T. Hunter P.274 No.272 corner gone. Found stake set west 184 links when original stake was standing; reset stake 184 lks. East of road stake. 16 south set temp stake M&L 19.99, 16 center SW 1/4 27 set stake inter lines - measure north 19.95 - 19.95.

4-1890 T. Fraser P.438 No.425 corner missing for years. Set stake M&L 40.021/6, 16 south set stake M&L 20.011/12. Stake line east.

6-1903 C. Armstrong P.64B found stake 14" below surface. 11/2' SW of corner post. Set boulder 12x15x16 in place of stake. 16 west set stake M&L 19.82. 16 south set flint type boulder stone 10x12x14 M&L 19.97 - 16 center SE1/4 27 set Lime stone 2x12x14 inters lines.

11-1961 J. Kerr Book 83 P.32, boulder found and used many years. Set 1"x36" pipe as corner with boulder witness. 1/16 corner 1/2" steel rod M&L 1319.94. RPs-Spud in tele pole NE 69.55'. Spud in tele pole SE 60.0'. CSD in SW side pp#38567 SE 55.75'. Chis "+" in conc headwall SW 32.02.

11-27-1963 John Kerr, Set CIM over 1"x36" pipe. RPs-corner post of fence running south E 3.0, Boulder east of corner; electric fence post just west of corner; .

7-17-1974 County Surveyor at 1/16th corner South dug up 1/2" rod - set 1/2" pipe over it.

9-29-1989 County Surveyor found CIM leaning, set sign & post 1.0' north.

10-6-1989 County Surveyor removed CIM, dug down to 1" pipe, set cast iron cap on telspar pipe over 1" pipe.

8-2-2000 Mn/DOT found cast iron cap on telspar pipe in good condition up 0.3'

10-2-2000 County Surveyor found cast iron cap on telspar pipe in good condition up 0.3'.

10-2-2000 1/16 south 1/4 cor 26-27. County Surveyor found 5/8" pipe w/cap at surface in good condition. Set ref pipe and tied out corner. Ref pipe SE 98.62'

3-4-2002 Mn/DOT survey crew found monument in good condition.

2-23-2004 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.