Certificate of Location of Government Corner

ID#: 642704 **Description:** 1/4 SEC COR 27 34 64 **Date Set:** 7/17/74 **County:** Olmsted

Section: 27 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 63' west of west edge of hole #2 fairway
County Survey Disk in SE side 20" Poplar SSW 68.89'
Post w/sign 73 1/2' west
This corner is located by GPS reference stations "WC #2 A & B"

Corner History:

1854 Gov't Notes W.B. Yerby, East Random 27 & 34, 40.00 set temp post in marsh west between 27 & 34 8° 27' E. 39.84 point for post in marsh. 48.0 set section corner. Burr Oak 10N 118 W 36 lks. Burr Oak 6S 66W 79 lks.

5-1875 T. Hunter P.274, No.272. No corner. Measure and run line. Set marked stake M&L. 39.761/2 (2624.49). 16 west set temp stake M&L 19.881/4 (1312.575'), 16 east set marked stake M&L 19.881/4, 16 north set marked stake M&L 19.981/2, 16 center SE1/4 27 set stake M&L 19.88 on E-W 1/16 line, 16 center SW1/4 27 set stake intersecting lines.

1882 16 center NW1/4 34 found fence corner set on inters lines, 16 south set stake M&L 19.981/4, 16 center NE1/4 34 M&L 19.97 on N-S 1/16 line.

6-1903 C. Armstrong P. 64B. No corner found. Set temp point for line north M&L 39.80 (2626.8)
16 east found Hunters stake which was OK on measure, but 6n south of direct line of section corner.

8-4-1972 County Surveyor ran electronic traverse from 27-28-33-34 to 26-27-34-35, measure 5245.64 1/2 2622.82.

8-7-1972 County Surveyor found large boulder (1/16 west of 26-27-34-35) 1.3' south of computed line and rear exact 1/4 distance between section corner 1311.41 set heavy axle with lug on each end 1 1/4" to 1 1/2" x 28" on exact section line and 1/4 distance above. Continued line and electronic measure west and set 1/4 27-34 in golf course at 2622.82 (RH2625.15). Set 5/8" rod with gear below monument. Set CIM below surface 241.6 SE'ly to 40D on south side blazed cottonwood. 402.75 NNW'ly to 20D on E side large 24" + lone red oak. May use corner over CIM at center 34 for line to S1/4 34. Corrected measure of section line 5246.84 corrected to 5245.64. 1/16 cor. Left as is (Could go east .3')

7-17-1974 County Surveyor reset CIM over 5/8" rod .6' east of 1972 position.

10-1985 County Surveyor found CIM in good condition.

8-16-2001 Mn/DOT survey crew found CIM in good condition.

7-14-2005 County Surveyor found CIM in good condition down 0.3'. Monument falls 63' west of west edge of fairway hole #2. CSD with concrete nail in 20" Poplar in SE side SSW 68.89' and set sign & post 73 1/2' west. Both sign and tree are along east side of stream.