Certificate of Location of Government Corner

ID#: 642904 **Description:** 1/4 SEC COR 29 32 64 **Date Set:** 10/12/89 **County:** Olmsted

Section: 29 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of twp road west and 48 1/2' east of centerline of driveway north
County highway disk in PP #25142 SW 71.28'
Bottle cap in PP #11687 NNW (slope meas) 129.97'
This corner is located by GPS measurement

Corner History:

1854 - Gov't Notes - W.B. Yerby 40.00 set a temporary section post. West between 29 & 32 8° 50' E.
40.17 1/2 set a section post. Burr Oak 10 N 38 E 63 lks. Burr Oak 4 S68 W 90 lks.

5-1874 T. Hunter, P. 252 No. 252 bearing trees gone, found stub of old stake in line fence running east. 48 lks. West of fence corner.

5-1877 T. Hunter, P. 314 No. 308 found stake set P. 252. 16 west set stake M&L 20.15. 16 north set stake M&L 19.91. 16 east set temp stake M&L 20.09. 16 center SW1/4 set stake M&L 19.88 on N-S 1/16 line, also inters. Lines. 16 center SE1/4 set stake inters. Lines.

5-1895 W. Fraser P. 572, No. 524 found stake P.252 set stone 2x8x18 with stake. 16 north found stake P. 314 set iron stake with boulder by its side M&L 19.91. 16 west set boulder M&L 20.15 - couldn't find Hunters stake. 16 east set stone 2x8x18 M&L 20.10. 16 center SW1/4 29 drove stake with stone by side M&L N-S1/16 line 19.88 - didn't check if still inters. Lines.

1936 county highway department B.#81 Pg. 47 Found boulder with + on it and old stake, by measuring south from stone monument at center 29 to 1/16 corner (old stake set in concrete distance 1312.5, pushed line south to find corner.

1939 county highway department B.103, P.53, found L stone 18x4x12 & stake.

1960 B.232, P.4 found stone boulder, Sp tele pole N 26.85, measure south 5292.9.

6-1963 J. Kerr found boulder, set CIM over it. Corner very near in line fence north & center road west. Disc power pole SW 71.3, Disc tile pole SE 42.0.

8-24-1970 County Surveyor run line from north, found CIM in place wrong. Reset CIM over findings. RPs-old disc in pp# 25141 SE 36.92, old disc in pp# 25142 NW side up 5" SW 71.34, NW corner new house foundation Slope meas. SW 157.15, pepsi cap on W side tele cable pole terminal N 31.6, "Like" bottle cap on NE side pp# 11687 slope meas NNW 129.9.

8-1-1972 County Surveyor, Zap from CIM over true original stone found east to CIM set over broken concrete monument found 6-1964. R.W. Fraser stone 2x8x18 M&L 20.10 1326.6 2653.2. Co. Hwy. 2637.7 from point 2.57 west of true corner. Measure as is 2637.56 with 1/16 fence south about 1324'± from 1/4 29-32 which is new and slightly curved. Will dig with tractor up to a rod east of CIM.

10-2-1989 County Surveyor found CIM in gravel road leaning badly, tel cable pole terminal gone.

10-12-1989 County Surveyor dug out CIM with jackhammer (broken in 3 places, down 28" found tel cable on east side. Set CIM over 3/4" iron over original stone.

3-11-2003 County Surveyor found CIM down 0.5' in good condition.

3-8-2004 County Surveyor found CIM down 0.5' in good condition.