Certificate of Location of Government Corner

ID#: 643105 **Description:** SW SEC COR 31 64 **Date Set:** 7/13/2005 **County:** Olmsted

Section: 31 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of twp road west, in centerline of twp road north and 2 1/2' west of centerline of twp road south
Bottle cap in PP #7243 SE 46.18'
County Survey Disk in PP brace pole SW 55.87'
County Survey Disk in PP #43764 NW 54.84'
SW corner square tele box NW 66.65'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, Karrick, 80.00 set section post for corner to twp 105-106. RPs-Black Oak 14N 371/2 W 18°. Burr Oak 10S 36 E 5°. Burr Oak 10S 63 W 73°. Burr Oak 14N 781/2 E 346.

5-1873 T. Hunter P.220 No.224, Found stake, measure north 40.02 to stake N10'W. 1/16 west set perm stake M&L 20.15 S88° 40'E.

1875 State law required that monuments be set at township corners. Thomas Hunter, County Surveyor, placed stone monuments as required.

6-1877 T. Hunter P.315 No.309, Found stake, tested SE Bearing tree & SW Bearing tree stump, Measure east 38.83 to proper distance of S1/4 3 78.47 to SE 31 gov't 79.18.

3-9-1900 R. Fraser P.652 No.5821/2, Found township engraved monument. Measure south, over ran 11/2 links 40.011/2.

8-28-1969 J. Kerr - Set corner 4' west and 1.6' north of original 00 in center roads. Lines fair with road north, good with roads E & W and 5' west of road south. Final measurements - 1/16 fence N running east 1320.7 near record which is 1/4 distance to NE cor 36 5284.5. Distance west to S1/4 36 as set 2660.0 with 1' of record 2659.0. Distance west to 1/16 fence north 1332. Set new chrome 120D at 1332 in exact line fence no on exact line between twp corner and S1/4 36 as set. Nail comes 3' ± no center traveled road.

11-4-1969 J. Kerr set CIM with iron below

10-13-1989 County Surveyor found R.R. Spike.

10-19-1989 County Surveyor removed R.R. spike, found CIM down 12".

2-7-2005 County Surveyor found CIM w/o head down 1.4' in good condition.

7-13-2005 County Surveyor found CIM without head down 1.4' in good condition. Removed CIM and found 3/4" rerod down 3' in good condition and removed. Set 6' telspar pipe w/cast iron cap down 0.4'.

3-20-2006 County survey crew found cast iron cap on telspar pipe down 0.4' in good condition.