Certificate of Location of Government Corner

ID#: 643606 **Description:** 1/4 SEC COR 35 36 64 **Date Set:** 5/25/2010 **County:** Olmsted

Section: 36 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The corner falls 6' east of centerline of CSAH 20 and 8' north of centerline of residential driveway west
County Survey Disk in CP E 48.23'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, W.B. Yerby - 40.00 set a section post. RPs-Black Oak 12 S40 E29 lks. Burr Oak 10 S25 W39 lks.

3-1857 Thomas Hunter, P.22, No.35 used 1/4 corner. 1/16 west 19.90 chains M&L to center section. Bearing Trees: N 621/2°W 123 lks., S 311/2°W 186 lks.

6-1863 P.C. Compton, Pg. 72 No. 104, Shows 1/4 corner, used to set center 36 at intersecting lines.

6-1878 T. Hunter, Book 5, Pg. 79 Unrecorded survey section 35 for James Ryan. At "H" E1/4 corner 35 found remains of old stake in center of road which agreed with measurements from stumps of Bearing Trees. Set stone 24"x10"x3". Measure west 19.871/2 to 1/16 corner then 19.871/2 to center 35, measure north 19.861/2 - 19.861/2.

5-18-1977 County Surveyor removed 8"x3/4" iron rod. Reset 1/2"x30" pipe 6'E of centerline N-S road. RPs-C.S.D. in 4" square corner post E 48.23'. CSD in 4" square corner post NE 66.43'.

8-16-2001 Mn/DOT survey crew found pipe in good condition.

3-17-2003 County Survey Crew found pk nail at surface, nail was 0.15' North and 0.1' East of 1/4 rod found down 0.3'. Rod was pounded inside of 1/2" pipe which was down 1.4', removed both. Set 5' telspar w/CIC down 0.1' from ties taken to pipe.

2-23-2004 County Survey Crew found telspar pipe w/CIC in good condition.

5-27-2008 County Survey Crew found cast iron cap on telspar pipe at surface bent. Removed bent portion of pipe and set new cap at surface.

5-25-2010 County Survey Crew set 1" square pipe w/cap at surface from GPS coordinates.