Certificate of Location of Government Corner

ID#: 650805 **Description:** SEC COR 7 8 17 18 65 **Date Set:** 9/4/1973 **County:** Olmsted

Section: 08 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 4' west of centerline of N-S twp road and 3' north of fence east
Bottle cap in PP #39194 E 38.62'
County highway disk in 8" Burr Oak SW 60.45'
County Survey Disk in 14" Burr Oak W 73.60'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: North between section 17 & 18 80.00 chs. Set section corner post. Erected mound with trench, pits, charred stakes, and Osage orange seeds at each angle.

5-1893 William Fraser (P.508 No.477), County Surveyor, measured from S.E. Cor 18 to W. 1/4 cor. 8 and N.W. Cor. 18 to N.E. Cor. 17. Set 6"x9"x15" stone at proportionate Gov't measure. Set 1/16 west midway and on line.

5-1893 William Fraser (P.510 No.478) found stone p.508.

7-1969 John Kerr, County Surveyor, dug but could not find corner. Set C.I.M. over 15½" pipe on line from S.E. Cor. 18 over 1/16 north (found) and in line with fence east. (Did not have 1/4 Cor. 17-18 at this time)

10-1-1970 County Surveyor found stone at 1/4 Cor. 17-18. Double line and measure from S.E. Cor. 18 over 1/4 Cor. 17-18 and point came .72' west and 3.84' north of John Kerr's C.I.M. This location also fits line and measure from old post found 3' deep at 1/16 west.

9-4-1973 County Surveyor removed Kerr's C.I.M. and reset .72' west and 3.84' north.

7-14-1980 County Surveyor retied corner before road grading. Checked old RP's: Pepsi cap in South side pp #39194 ESE 38.60'. 20d in hub on East side blazed 20" Burr Oak SW 65.42'. 20d in hub on South side blazed 14" Burr Oak WSW 40.77'. New RP's: Spike and CSD S side 14" Burr Oak West 73.70' . Spike and CSDNW side 8" Burr Oak SW 60.40'. Before road grading this corner 6' West of center of road and 3' North of fence East.

11-9-1999 County Surveyor found CIM in good condition 7" deep in crushed rock.

2-1-2005 County Surveyor found CIM down 0.8' in good condition. Checked reference ties.

7-13-2006 County Surveyor found CIM in good condition down 0.7'.

10-2-2006 County Surveyor found CIM down 0.7' in good condition.