Certificate of Location of Government Corner

ID#: 650806 **Description:** 1/4 SEC COR 7 8 65 **Date Set:** 7/13/2006 **County:** Olmsted

Section: 08 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of north-south township road (109th Ave SW) and 1' south of centerline of township road (15th St SW) west
The monument is down 0.4'
1/2" rod on E-W 1/4 line of Section 7 extended E 60.00'
County Survey Disc in NW side PP SW 41.21'
County Survey Disc in SE side PP SW 41.16'
This corner is located by GPS measurement

Corner History:

6-9-1854 Michael G. Karrick, Deputy Surveyor, measured north 40.00 chains between Sections 7 and 8. Set quarter section post. RPs - 6" Bur Oak N18-1/2°W 516 links (340.56'), 7" Bur Oak N45°E 415 links (273.90').

6-5-1884 Thomas Hunter, County Surveyor, (Old Field Book No. 14, Page 20), surveyed the road on the E-W 1/4 line Section 7 and shows the East 1/4 Corner Section 7 midway (40.02 chains), but gives no description or explanation.

5-26-1893 William Fraser, Deputy County Surveyor, (Book A, Pages 508-509, Survey No. 477), "found a stone as corner that was planted by Thomas Hunter."

7-8-1910 Charles Larson, County Surveyor, (Book B, Pages 134-135), set iron stake on E-W 1/4 line Section 7 but does not indicate what was used at Center 7 or East 1/4 Corner 7.

5-18-1930 John Kerr, County Surveyor, (Kerr Field Book No. 3, Pages 29-30), shows stake at 1/4 Corner 7-8.

9-16-1970 Roger Brand, County Surveyor, dug and found nothing.

7-21-1980 County Survey Crew dug and found nothing.

7-25-1980 Roger Brand, County Surveyor, dug again and found nothing. Set 5/8"x15" rod as the corner. This corner set north-south on line from W 1/4 Corner 7 over Center 7 and set east-west averaging 1/16th fences in the NE 1/4 and SE 1/4. The corner falls 3' west of centerline of north-south township road and 4' south of centerline of township road west prior to grading. RPs - 1/2" rod on E-W 1/4 line Section 7 extended E 60.00', County Survey Disc in PP #8595 SW 42.59'.

2-1-2005 County Survey Crew found 5/8" rod down 0.4' in good condition. RP - County Survey Disc in NW side new power pole SW 41.21'.

7-13-2006 County Survey Crew found 5/8" rod in good condition down 0.4'. Set Cast Iron Cap on 4' telspar pipe over rod down 0.4'. The corner falls in centerline of north-south township road (109th Ave SW) and 1' south of centerline of township road (15th St SW) west. RP - County Survey Disc in SE side of PP SW 41.16'.

10-2-2006 County Survey Crew found Cast Iron Cap on telspar pipe down 0.4' in good condition and measured its position using GPS.