Certificate of Location of Government Corner

ID#: 652806 **Description:** 1/4 SEC COR 28 29 65 **Date Set:** 10/17/2003 **County:** Olmsted

Section: 28 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The cast iron cap on telspar pipe is down 0.3'
The corner falls 4 1/2' west of centerline of CR 150 north
County Survey Disk in W side PP NNW 53.38'
T-cross in E culv. headwall NNE 68.04'
Ref. Point NNE 48.52'
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karrick 40.00 set quarter section post. Burr Oak 10 S 20 W 223. Aspen 10 S 50 E 306. 40.50 creek 4 lks wide runs NE and leave Aspen thicket bears NW.

6-1905 W. Fraser (Bk.B P.92) corner gone, reset it with a stake and stone midway and on line.

12-1939 J. Kerr (Bk.B P.556) found limestone and set and iron rod on the West side of stone.

4-1953 county highway department found the stone and set an 8"x 8"x30" capped conc. monu.

7-1972 County Surveyor dug and found the limestone but not the iron rod J. Kerr set beside it. Reset the C. Hwy. Dept. conc. monu. over a 5/8" by 12" iron with a Cast Iron Monu. on top of that.

Note: this is a correction of a corner. The limestone was .43' N and .47' E of the conc. monu.

3-8-2000 County Surveyor found CIM down 1.2' with head broken off. Removed CIM and set 5/8" x 24" rerod down 0.3'.

4-22-2002 County Surveyor found 5/8" rerod down 0.2' in good condition. Set 5/8" rod as ref point and tied out corner for CR 150 grading. Removed 5/8" rerod.

10-17-2003 County Surveyor set CIC on 3.0' telspar pipe down 0.3' from 2002 construction.

2-16-2010 County survey crew found cast iron cap on telspar pipe down 0.3' in good condition