Certificate of Location of Government Corner

ID#: 653406 **Description:** 1/4 SEC COR 33 34 65 **Date Set:** 4/8/2010 **County:** Olmsted

Section: 34 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road, 9' south of fence west, 255' south of centerline of twp road east and down 0.5'
Spike in Pine NE 60.31'
County Survey Disk in 15" Oak WSW 80.39'
County Survey Disk in PP NW 43.92'
County Survey Disk in 15" Pine 49.09'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes Michael Karrick, Deputy Surveyor North between section 33 and 34. 40.00 chs. Set quarter section post in mound with trench and pits and charred stake and planted Osage orange seeds NE and SW.

6-1932 John Kerr, (B.8 P.14) used a point (no description) midway and on line between the section corners to set the 1/16th North.

12-1972 County Surveyor set a railroad spike midway and on line. Found a 1" iron 6.7' South and .43' East of the railroad spike.

7-27-1976 County Surveyor dug with the backhoe at the midway and on line location. Found 10"x10" black mark with wood pieces extended well down into the clay. Accepted the mark as the stake location and drove a 1½"x3' pipe in the stake hole. The pipe is 1.6' West and 2.0' North of the railroad spike (removed). Dug out the 1" shaft and found that it was not set over anything.

3-23-1977 County Surveyor set a CIM over the pipe set in 1976. RP's CSD in power pole NW 43.92 (1981). Spike and CSD in 15" Oak WSW 80.39.

9-24-1987 County Surveyor CIM was leaning badly, reset and took new ties as shown in pencil as 1987 ties.

3-7-2000 County Survey Crew found CIM down 0.2' in good condition.

4-8-2010 County Survey Crew found CIM down 0.2' leaning east. Took ties and removed. Found 1 1/2" pipe down 1.3' in good condition. Took ties and removed. Set a 5' telspar pipe w/Cast Iron Cap down 0.5' at pipe location.