Certificate of Location of Government Corner

ID#: 710705 **Description:** W SEC COR 7 18 71 **Date Set:** 1/13/2006 **County:** Olmsted

Section: 07 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fences north and west
Post w/sign 2' east
This corner is located by GPS reference stations "Albers A & B"

Corner History:

9-1853 Gov't Notes: Set post for corner. BT's: Burr Oak 8" S 63°W 80 lks, Burr Oak 8" N 44°W 156 links, Burr Oak 12" S 67°E 243 links, Burr Oak 11" N 87°E 243 links.

6-1877 T. Hunter (P.317 No.311) "found stake standing and also SW witness tree. 8" Burr Oak S 63W 52.8' tested stake by said witness tree and found it correct. 16E set marked stake on line to stone at S 1/4 7 line short 11 lks of gov't meas R 39.59 act 39.48. Set corner at 19.53-1/2 1289.31 and 19.94-1/2 1316.37.

11-1892 Thos. Fraser (P.500 No.471) found stone set by Mr. T.Udell and Mr. Pervis in place of gov't stake when stake was standing. 16 S planted boulder M&L 19.96-3/4 1317.85.

6-1893 W.Fraser (P.516 No.482) found stone P.500 left as found. Meas south to stone set M&L 39.92-1/2 2635.05.

7-1933 county highway department B.73 P.19 shows corner in place no disc, no references. Corner tied to extended tangent of road at that time as it intersects N-S section line 755.9 at station 121 + 24.9 at angle 73° 15'.

8-1-1973 County Surveyor walked to corner with probe and shovel finally figured which fence was correct. No B trees in heavy brush on S side found limestone on top rather short but could be corner.

11-8-1976 County Surveyor double line and measure from E 13-24 over E-1/4 13. Point came on E side of corner post to fences N and W. Dug 3' x 3' on E side of post and found the base of two old posts. Set 1/2" x 2' rod in old post which later calc .24 S and .22 W of exact double. Will not set final corner until 1/16th S is dug again.

12-15-2005 County Surveyor found 1/2" iron rod up 0.3' in good condition. Monument falls inline w/fence west and 1.0' east of fence north.

1-13-2006 County Surveyor found 1/2" rerod up 0.5' in good condition. Removed 1/2" rerod and set 5' telspar pipe w/cast iron cap up 0.2' at 1/2" rerod position. Set post w/sign.