Certificate of Location of Government Corner

ID#: 712705 **Description:** SEC COR 27 28 33 34 71 **Date Set:** 6/22/2011 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls in centerline crack of CSAH 10 and in centerline of E-W twp road
The monument is at the surface
Traverse point (Munz 1" square pipe/cap) SW 40.56'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 33 and 34. 80.00 chs. Set section corner post in mound of earth and sod. Deposited charcoal, made trench and pits, planted osage orange seed N.W. and S.E. of trench.

4-1857 Road Survey (E.P. Bircher, Surveyor, and Thomas Hunter, Deputy) used the section post. Measured 39.87 chs. (2631.42') to ¼ Cor. 27-28 and 79.12 chs. (5221.92) South to S.Sec. Cor. 33-34.

4-1898 William Fraser (P. 625 No. 569), County Surveyor, set a temporary point in the center of the N-S road and at prorated Gov't Measure from ¼ Cor. 21-22 to S. Sec. Cor. 33-34.

1913 County Highway Department (B.1 P.57) referenced a point (not described) and measured 2647.0' North to the E-W fence at ¼ Cor. 27-28.

1917 County Highway Department (B.21 P.38) referenced a point (not described).

1921 County Highway Department (B. 168 P.11) shows a 1"x2" stake and nail at the corner. Measured 2649.2' North to ¼ Cor. 27-28 (not described) and 5252.3' South to S. Sec. Cor. 33-34.

10-1976 Harry S. Johnson and Sons Co. found a 1¼" pipe.

8-22-1977 County Surveyor dug along side a 1¼" pipe found in the centerline of the roads N-S-E-W. The area had been cut in the road construction. Found nothing further. Measured 2649'± to the E-W fence at ¼ Cor. 27-28 and 5253.36' South to S. Sec. Cor. 33-34.

8-23-1977 County Surveyor drove the 1¼" pipe down and set a C.I.M. over it as the corner.

9-23-1988 County Surveyor found C.I.M. in good condition, checked ties.

11-15-2005 County Surveyor found CIM in good condition down 0.6', took local ties and removed. Found 1 1/4' pipe down 1.9', ties checked w/CIM.

11-16-2005 County Surveyor set 1" square pipe w/cap at surface from local ties taken from CIM. Did not check ties due to high winds.

6-22-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates.