Certificate of Location of Government Corner

ID#: 713405 **Description:** S SEC COR 33 34 71 **Date Set:** 6/17/2011 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls 0.1' west of centerline crack of CSAH 10 and 0.2' north of centerline crack of CSAH 9
The monument is at the surface
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 3 and 34. 80.00 chs. Set post and drove charred stake. Built mound with trench.

4-1898 William Fraser, (P. 625 No. 567), County Surveyor, found wood stake in the center of the road. Set stone 4" x 7" x 27".

10-1902 William Fraser (P. 26B) found stone.

1937 county highway department (B. 94 P. 78) found 1 1/2" pipe with small limestones around pipe.

10-17-1974 County Surveyor, found the remaining 12" of the recorded stone 2' deep in intersection. Placed a flat iron on the west side and the base of a C.I.M. on the east side of the stone. Placed a C.I.M. over all. The corner location is 1.2' south and 1.1' east of the pipe with a 5/8" rod in it that was at the surface. There was another pipe down deep under the pipe with rod.

9-23-88 County Surveyor found C.I.M. in good condition.

7-11-1995 County Surveyor found CIM down 0.6' in good condition.

7-15-1998 County Surveyor found CIM in good condition 8" deep in CSAH 10.

11-7-2005 County Surveyor found CIM in good condition down 0.8'.

11-8-2005 County Surveyor took local ties to CIM, removed. Did not try to locate stone.

11-9-2005 County Surveyor set 1" square pipe w/cap at surface from ties taken from CIM. Did not check ties due to high wind.

3-6-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

6-17-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates