Certificate of Location of Government Corner

ID#: 721309 **Description:** SEC CEN 13 72 **Date Set:** 7/26/73 **County:** Olmsted

Section: 13 **Township:** 107N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1 1/4" pipe

Reference Ties:

The corner falls 5' west of centerline of CR 107 and 4' north of fence east
County highway disk in CP W 20.45'
County highway disk in fence post SW 47.35'
This corner is located by GPS reference stations "Logan Creek A & B"

Corner History:

6-15-1893 W. Fraser P.516 No.482 drove iron stake 3 feet long at true inters lines. 1/16 north found stone set by Hillman in early days as line west, accepted by all, no meas. 1/16 center NW 1/4 13 found stone set by Hillman. Set stakes west above 1/16 corner 9.97 then 4.98-1/2 then 4.98-1/2 to stone set by Hillman and accepted.

7-23-1973 County Surveyor searched with detector found nail and wire no iron rod uncertain as to E-W. Good established fence east.

7-26-1973 County Surveyor set point in east road ditch as random on traverse for easier computation (see field notes). Dug after computing location and easily found top of pipe as recorded. Set 1-1/4x2' iron pipe as final corner (over lower pipe) which lies 5' west center N-S road, 4' north fence running E 63.8 west on apparent 1/4 line to tiny deep blaze on south side 18" burr oak lightly blazed. 200.0 SSW to center 28" pine easterly of pines not all in same row or 2 definate rows likely about 50 or 60 feet west of road centerline.

6-15-1976 K. Ewers found and used 1 1/4" pipe.

9-1978 county highway department found pipe in bridge survey (sta. 221+00). Took add'n RP's: Spk and disc cor fe post west 20.45'. Spk and disc in fence post SW 47.35'.

9-29-1999 Brand & Massey Surveying Inc. found and used 1 1/2" iron pipe at center of section 13.

8-9-2007 County Surveyor found 1 1/2" pipe down 0.5' in good condition.