Certificate of Location of Government Corner

ID#: 723305 **Description:** S SEC COR 32 33 72 **Date Set:** 6/30/2005 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" brass plug with punch mark

Reference Ties:

The corner falls in centerline of CSAH 9, 1' east of centerline of twp road south and 4' west of centerline of twp road north
County Survey Disk in W side PP #258 NW 76.52'
Punch hole in W end 18" CMP SSW 48.96'
Punch hole in E end 18" CMP SSE 48.40'
Punch hole in E end 18" CMP NNE 47.97'
County highway disk in E side PP #257 SW 70.15'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor west between sections 4 and 33. 80.00 chs. Set post and drove charred stake. Built mound with trench and planted plumb SE and Apple seed NE.

6-1873 Thomas Hunter (P.226 No. 229), County Surveyor, found large cedar stake in center of the road with stones on the north and south liines.

5-1880 John Fraser (P.364 No.355), County Surveyor found large cedar stake of Survey No. 229.

9-1930 John Kerr (B.3 P.56), County Surveyor found cedar stake. Drove 7' long rod down through stake center.

1935 county highway department (B75 P.20) states corner found.

1937 county highway department (B.88 P.77) found iron fence post with can and bottle.

6-1957 county highway department (B.206 P.3) had 3/4" drill steel as corner.

6-3-1970 County Surveyor dug out drill steel. Found John Kerr's steel fence post down 2.6'. Set 1/2" x2' rod over at road level.

11-20-1974 County Surveyor found county highway department P.I. Rod at corner location so accepted as corner.

6-12-2001 County Surveyor found county highway department P.I. Rod w/punch mark at surface in good condition.

An analysis of the above record indicates that the P.I. Rod is the perpetuation of the Original Public Land Survey.

7-15-2003 County Surveyor found copper plug with punch mark at surface in good condition.

6-30-2005 County Surveyor set a brass plug with punch mark at surface from coordinates. Monument falls in centerline crack of CR 9, 4' west of centerline road north and 1.0' east of centerline road south. Rechecked all ties and updated distances. Disc with nail in east side of PP #257 SW 70.15'.

4-27-2009 County Surveyor found 5/8" brass plug w/punch mark at surface in good condition.