Certificate of Location of Government Corner

ID#: 723605 **Description:** S SEC COR 35 36 72 **Date Set:** 11/29/1994 **County:** Olmsted

Section: 36 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9 and in line with row of pines north
SE corner main house foundation NW 146.0'
Center 6" Maple NW 96.7'
County Survey Disk in PP #601 NE 50.32'
County highway disk in W side of 4th Pine in row of pines N 64.08'
County Survey Disk in PP SE 59.59'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 1 and 36. 80.00 chs. Set post and dug trench per instructions for corner to sections 1,2,35 & 36. Burr Oak 6 in. N4&3/4°E 343 lks. Burr Oak 5 in. S21°W 56 lks.

6-1874 Thomas Hunter (P.247 No. 248), County Surveyor, found stone. Tested the stone with the S.W. bearing tree and proved it correct.

6-1893 William Fraser (P.517 No. 483), County Surveyor, found the stone P. 247.

9-1927 county highway department (B.48 P.33) found stone monument.

1938 county highway department (B. 94 P.2) found 4"x6"x24" limestone. Took references: Spike in corner fence post N. 34.2'; Spike in pine N.W. 78.6'.

6-1970 County Surveyor searched for the 1938 reference points. Found the stub of the corner post North which would place the corner about 2' North of the centerline of CR 9.

7-14-1976 County Surveyor dug with the backhoe. Found a 2"x2" hub over a black mark in the clay. Set a 1/2" x 2' rod to retain this location.

7-16-1976 County Surveyor set a C.I.M. over a 1/2" rod as the corner at the location of the hub found 7-14-1976. The corner falls approx. 2.3' North of the centerline of CR 9 and in line with the row of pines North.

5-27-1993 county highway department took grading ties to CIM before construction on CSAH 9.

11-30-1993 county highway department set 3/8" iron in crushed rock CSAH 9 @ corner location.

11-29-1994 county highway department set 5/8" copper plug in concrete CSAH 9 as final corner.

12-12-2006 County Surveyor found 5/8" copper plug at surface in good condition.

3-6-2007 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.