Certificate of Location of Government Corner

ID#: 731205 **Description:** SEC COR 11 12 13 14 73 **Date Set:** 9/7/2011 **County:** Olmsted

Section: 12 **Township:** 107N **Range:** 13W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The corner falls 3' east of centerline of N-S twp road and 4' north of fence east
County Survey Disk in E side PP #19579 SW 139.43'
County Survey Disk in CP ESE 30.85'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 80.00 set section corner post to 11-12-13-14, made trench. 10" Burr Oak N43 W439 links, 10" Burr Oak N38 E204 links, 10" Burr Oak S68 W370 links.

6-1857 J. Fellows P.29, No.45, Used corner, measure W 39.55, measure south 40.0'.

9-2-1969 J. Kerr accepted 1/16 fence east as correct NE corner 14 lost.

11-28-1969 J. Kerr found W1/4 11, cen 11 & both 1/16 stones on line. Set CIM at 1/4 11-12.

6-7-1976 County Surveyor dug for the corner with the backhoe but did not find anything.

9-2-1976 County Surveyor set CIM over 1/2"x2' rod as the corner by double proportionate measure 1/4 Cor. 13-14 to 1/4 Cor. 11-12 and 1/4 Cor. 11-14 to 1/4 Cor. 12-13.

10-8-1996 County Surveyor found CIM 11" deep in N-S twp road ± 4' north of fence east and ± 3' east of centerline.

8-4-2011 County survey crew checked the tie to power pole #19579 and found it is about 1' off

9-7-2011 County survey crew found CIM down 1'. The 1/2" rod which should have been under the CIM was found leaning alongside the CIM, indicating both monuments have been disturbed. Removed both monuments and set a 5' telspar pipe with cast iron cap using the following previously set reference ties:

County survey disk in east side of power pole #19579, SW 139.43'
County survey disk in corner post, ESE 30.85'

The dimensions from the newly set telspar pipe to the adjacent quarter section corners checked with what has been measured previously.