Certificate of Location of Government Corner

ID#: 732704 **Description:** 1/4 SEC COR 27 34 73 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2 1/2' east of centerline CSAH 11 and in centerline of E-W twp road
The monument is down 0.8'
Spike in CP SW 80.86'
Concrete nail in PP #41179 NW 62.37'
Concrete nail in PP #38658 NE 59.07'
Top center telephone box NE 50.55'
Ref pipe E 117.93'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.0 set temp sec post W on true line between section 27&34 8° 37'E. 40.00 set section post in mound, made trench, planted Osage Orange seed N&S of trench.

5-15-1876 T. Hunter P.292, No.287 found stone. 16 w set stake. 16 e set stone 5"x14"x18" M&L 19.871/2 (1311.75).

5-17-1876 T. Hunter, P.293, No.288, found stone P.292.

5-1876 T. Hunter (Book A, Page 293, No. 288) found the stones at 1/4 Cor. 27-34 and the 1/16th East as described in Survey No. 287.

1960 County Highway Department found nothing on corner on Borst survey, assumed point for corner.

1962 County Highway Department B.274 P.6, Set assumed 60D, measure south 2613.9. Measure north to CIM center 27 2634.66.

8-26-1968 Kerr (card) found Hunter's stone at the 1/16th East and also at Sec. Cor. 26-27-34-35.

11-23-1973 County Surveyor set R.R. spike as temp corner. Found CIM at 26-27-34-35, found 1/16 pipe with, bent, reset. Set R.R. spike in blacktop Co. Rd. #11. Measure west from spike, cor comes 7.9' south of direct line.

7-27-1979 County Surveyor set a C.I.M. over a 1/2" x 18" iron pipe in place of the railroad spike set 11-23-1973.

7-28-1989 County Surveyor found CIM in good condition.

6-1994 County Surveyor found CIM set ref pt 1" sq. pipe w/cap east edge field drive east before cold recycling bituminous surface of C.R. #11.

11-14-1994 County Highway Department set 1" square pipe w/cap at surface from 1994 overlay tie out.

10-18-2005 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-20-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.